

Job #: 57950 /

VIN: 54DB4W1B9GS812813

14' LYNCOACH & TROJAN DRY VAN BODY, GAS 2016 - ISUZU NPR / NA

Specifications	
Year	2016
Make	Isuzu
Model	NPR
Date of Inspection	07/28/2023
Location of Inspection	4313 Cameron Street, Lafayette, LA, 70506, USA
VIN	54DB4W1B9GS812813
GVWR	12,000 lb
Odometer	96,870
Engine Hours	N/A
EMS Warning Lights	No Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	See Notes
Passenger's Seat	See Notes
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Engine Serial Plate	Obstructed
Oil Dipstick	Good Color / Good Level
Coolant Level	Obstructed
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Cylinders	N/A
Left Steer Tire Condition	See Notes
Left Steer Tire Brand	BFGoodrich
Left Steer Tire Size	LT215/85R16
Left Outer Drive Tire Condition	See Notes
Left Outer Drive Tire Brand	BFGoodrich
Left Outer Drive Tire Size	LT215/85R16



Video Inspection Link

https://app.aspenfieldservices.com/jobs/video/RCkwYteLom6KiZXKn

Notes / Description

The sheet metal on the right side of the box is dented and bent and the top right corner of the box is dented. The plastic face cover is cracked on the instrument cluster. The driver and passenger bottom seat cushions have holes in them. The left side cover is missing on the dash. The steering column plastics are separating. The floor mat cover is ripped and the material is loose under the seat. The paint is worn on the left grab iron and chipped in the the right grab iron in the cab. The cover is missing from the door panel. All tires are worn and the left steer tire has a split in its center. The rear right brake light lens is broken. The brakes sound squeaky when activated.



Left Inner Drive Tire Condition	See Notes
Right Steer Tire Condition	See Notes
Right Steer Tire Brand	Cooper
Right Steer Tire Size	LT215/85R16
Right Outer Drive Tire Condition	See Notes
Right Outer Drive Tire Brand	BFGoodrich
Right Outer Drive Tire Size	LT215/85R16
Right Inner Drive Tire Condition	See Notes
Axle Information	F: 4,860 lbs / R: 8,840 lbs
Transmission Information	Obstructed
Engine Information	Obstructed



Front Left / 07-28-2023



Front / 07-28-2023



Front Right / 07-28-2023



Right / 07-28-2023




VIN: 54DB4W1B9GS812813 / GVWR: 8,840 LB / Axle Information / 07-28-2023



Odometer: 96,870 / 07-28-2023



Driver's Seat / 07-28-2023



Passenger's Seat / 07-28-2023



Floorboard / 07-28-2023





Steering Wheel / 07-28-2023



Steps / 07-28-2023



Steps / 07-28-2023






Handrails / 07-28-2023



Exhaust Pipe / 07-28-2023



Left Outer Drive Tire Condition / 07-28-2023



Left Outer Drive Tire Brand / 07-28-2023



Left Outer Drive Tire Size / 07-28-2023



Left Inner Drive Tire Condition / Left Outer Drive Tire Condition / 07-28-2023



Suspension / 07-28-2023



Suspension / Axles / 07-28-2023



Right Outer Drive Tire Condition / 07-28-2023



Right Outer Drive Tire Brand / 07-28-2023




Right Outer Drive Tire Size / 07-28-2023



Right Inner Drive Tire Condition / Right Outer Drive Tire Condition / 07-28-2023




Suspension / 07-28-2023



Suspension / Axles / 07-28-2023



Right Steer Tire Condition / 07-28-2023



Right Steer Tire Brand / 07-28-2023



Suspension / Axles / 07-28-2023




07-28-2023



Left Steer Tire Size / 07-28-2023



Left Steer Tire Condition / 07-28-2023



Suspension / Axles / 07-28-2023




Engine Compartment / 07-28-2023



Engine Compartment / 07-28-2023



Engine Compartment / 07-28-2023



Oil Dipstick / 07-28-2023





Rear Lights / 07-28-2023