

Aspen Field Services Job #: 58371 / VIN: 54DK6S160JSG01208

2018 ISUZU FTR CHASSIS WITH 26' MORGAN DRY VAN BODY / N/A

Specifications	
Year	2018
Make	lsuzu
Model	FTR Chassis with 26' Morgan Dry Van Body
Date of Inspection	08/07/2023
Location of Inspection	61-50 Maurice Avenue, Maspeth, NY, 11378, USA
VIN	54DK6S160JSG01208
GVWR	25,950 lbs
Odometer	93,852
Engine Hours	5,858
EMS Warning Lights	Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	Engine Compartment
Engine Serial Plate	Obstructed
Oil Dipstick	Dark Color / Good Level
Coolant Level	See Notes
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	See Notes
Left Steer Tire Brand	Bridgestone
Left Steer Tire Size	11R22.5
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Bridgestone
Left Outer Drive Tire Size	11R22.5
Left Inner Drive Tire	No Damages Observed



Video Inspection Link

https://app.aspenfieldservices.com/jobs/video/KxzKJSwXhqrgFA3ZK

Notes / Description



Condition	
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Bridgestone
Right Steer Tire Size	11R22.5
Right Outer Drive Tire Condition	See Notes
Right Outer Drive Tire Brand	Bridgestone
Right Outer Drive Tire Size	11R22.5
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	Obstructed
Transmission Information	Obstructed
Engine Information	Obstructed

Visible Damages	
Paint	There is some graffiti art sprayed onto the box of the truck.
EMS Active Warnings	The EMS Screen shows active warnings.
Front Door	The front right door is dented.
Door Light	The door's light is scratched.
Fiberglass Panel	The fiberglass panel is broken below the right door.
Mud Flap	The front right mud flap is torn off.
Engine Oil	The engine oil is dark in color.
Coolant	The coolant is low in the reservoir.
Oil Hub Cap	The front wheel oil hub caps are leaking.
Left Steer Tire	The tire has weather cracks on the sidewall.
Right Outer Drive Tire	The tire tread is worn.
Windshield	The windshield is rock-chipped on the left side.
Backup Alarm	The alarm is not operational.



Front Left / 08-07-2023











Left / 08-07-2023





VIN: 54DK6S160JSG01208/ GVWR: 25,950 lbs / 08-07-2023

















Radio / A/C / Switches and Controls / 08-07-2023





Switches and Controls / Heated Mirrors / 08-07-2023





Switches and Controls / 08-07-2023




















Handrails / 08-07-2023






Engine Compartment / 08-07-2023





Coolant Level / 08-07-2023



Engine Compartment / 08-07-2023





Right Steer Tire Condition / 08-07-2023








Left Steer Tire Condition / 08-07-2023





Left Steer Tire Size / 08-07-2023



Suspension / Axles / 08-07-2023





Left Outer Drive Tire Condition / 08-07-2023





Left Outer Drive Tire Size / 08-07-2023





Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 08-07-2023





Right Outer Drive Tire Brand / 08-07-2023





Suspension / Axles / 08-07-2023



