

## DIESEL 2019 - ISUZU FTR, CAB AND CHASSIS / LA127625

Specifications	
Year	2019
Make	Isuzu
Model	FTR
Date of Inspection	08/17/2023
Location of Inspection	1463 US Hwy 22, Mountainside, NJ, 07092, USA
VIN	54DK6S164KSG00273
GVWR	25,950 lbs
Odometer	115,115
Engine Hours	4,222
EMS Warning Lights	Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	See Notes
Handrails	No Damages Observed
Exhaust Pipe	See Notes
Engine Compartment	No Damages Observed
Oil Dipstick	Dark Color / Good Level
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Bridgestone
Left Steer Tire Size	11R22.5
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Gripower
Left Outer Drive Tire Size	11R22.5
Left Inner Drive Tire Condition	No Damages Observed

### Equipment Photo



### Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/qxwnefpmTQYGJ8WbM>

### Notes / Description

The unit has temporary mud flaps installed on it and aftermarket rear light bracket have been installed on the rear.



## Aspen Field Services

Job #: 58895 /

VIN: 54DK6S164KSG00273

Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Bridgestone
Right Steer Tire Size	11R22.5
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	Gripower
Right Outer Drive Tire Size	11R22.5
Right Inner Drive Tire Condition	No Damages Observed
Axles Information	F: 19,000 LBS / R: 30,000 LBS
Transmission Information	Obstructed
Engine Information	Obstructed

### Visible Damages

Front Bumper	The bumper is dented on the right.
Right Step	The step is bent outwards.
Frame	The rear crossmember support has been cut out and removed.
EMS Warning Lights	The dash is showing the fuel filter service is due.
Instrument Cluster	The cluster plastic face cover is scratched.
Fire Extinguisher	the fire extinguisher is missing from its mount.
Panel Cover	The cover is missing on the dash in the center.
Glove Box	The lid will not latch shut.
Exhaust Flange	The flange and bolts are rusty.
Coolant	The coolant is low in the reservoir.
Engine Oil	The oil is dark in color.
Oil Hub Caps	The front right wheel oil hub cap is leaking.
Shocks	The front shocks are leaking.
Differentail Seal	The pinion seal is leaking on the differential.
Rear Right Outer Wheel	The wheel is bent on the lip.
Pulley	A belt or pulley squeaks when the unit is started.



# Aspen Field Services



Front Left / 08-17-2023



Front Right / 08-17-2023



# Aspen Field Services



Front / 08-17-2023



Right / 08-17-2023



# Aspen Field Services



Left / 08-17-2023



Rear / 08-17-2023



# Aspen Field Services



VIN: 54DK6S164KSG00273 / GVWR: 25,950 lbs / Axles Information / 08-17-2023



EMS Warning Lights / 08-17-2023



# Aspen Field Services



Engine Hours: 4,222 / Odometer: 115,115 / 08-17-2023



Cab Interior / 08-17-2023



# Aspen Field Services



Driver's Seat / 08-17-2023



Passenger's Seat / 08-17-2023



# Aspen Field Services



Cab Interior / 08-17-2023



Floorboard / 08-17-2023



# Aspen Field Services



Floorboard / Pedals / 08-17-2023



Steering Wheel / 08-17-2023



# Aspen Field Services



Switches and Controls / 08-17-2023



Switches and Controls / 08-17-2023



# Aspen Field Services



Switches and Controls / 08-17-2023



Radio / A/C / Switches and Controls / Heated Mirrors / 08-17-2023



# Aspen Field Services



Transmission / 08-17-2023



Steps / 08-17-2023



# Aspen Field Services



Handrails / 08-17-2023



Handrails / 08-17-2023



## Aspen Field Services



Handrails / 08-17-2023



Mirrors / 08-17-2023



# Aspen Field Services



Steps / 08-17-2023



Handrails / 08-17-2023



# Aspen Field Services



Handrails / 08-17-2023



Handrails / 08-17-2023



## Aspen Field Services



Mirrors / 08-17-2023



Mirrors / 08-17-2023



# Aspen Field Services



Exhaust Pipe / 08-17-2023



Engine Compartment / 08-17-2023



# Aspen Field Services



Coolant Level / 08-17-2023



Engine Compartment / 08-17-2023



# Aspen Field Services



Oil Dipstick / 08-17-2023



Front Lights / 08-17-2023



# Aspen Field Services



Rear Lights / 08-17-2023



Right Steer Tire Condition / 08-17-2023



## Aspen Field Services



Right Steer Tire Condition / 08-17-2023



Right Steer Tire Brand / 08-17-2023



# Aspen Field Services



Right Steer Tire Size / 08-17-2023



Suspension / Axles / 08-17-2023



# Aspen Field Services



Left Steer Tire Condition / 08-17-2023



Left Steer Tire Condition / 08-17-2023



## Aspen Field Services



Left Steer Tire Brand / 08-17-2023



Left Steer Tire Size / 08-17-2023



# Aspen Field Services



Suspension / Axles / 08-17-2023



Left Outer Drive Tire Condition / 08-17-2023



# Aspen Field Services



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 08-17-2023



Left Outer Drive Tire Brand / 08-17-2023



# Aspen Field Services



Left Outer Drive Tire Size / 08-17-2023



Suspension / Axles / 08-17-2023



## Aspen Field Services



Right Outer Drive Tire Condition / 08-17-2023



Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 08-17-2023



# Aspen Field Services



Right Outer Drive Tire Brand / 08-17-2023



Right Outer Drive Tire Size / 08-17-2023



## Aspen Field Services



Suspension / Axles / 08-17-2023