

20' TRANSIT BODY WITH RAMP, DIESEL 2019 ISUZU NRR / LA128159

Specifications	
Year	2019
Make	Isuzu
Model	NRR
Date of Inspection	08/15/2023
Location of Inspection	109 Lindberg Avenue, Methuen, MA, 01844
VIN	JALE5W165K7303765
GVWR	19,500 lbs
Odometer	133,791
Engine Hours	5,884
EMS Warning Lights	Active Warnings
Cab Interior	See Notes
Driver's Seat	See Notes
Passenger's Seat	See Notes
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	See Notes
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Good Level / Dark Color
Coolant Level	Low Level
Suspension	Leaf Spring - See Notes
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Roadmaster
Left Steer Tire Size	225/70R19.5
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Roadmaster
Left Outer Drive Tire Size	225/70R19.5
Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Roadmaster

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/qc93P8n3PqyoSYNc9>

Notes / Description



Aspen Field Services

Job #: 58878 /

VIN: JALE5W165K7303765

Right Steer Tire Size	225/70R19.5
Right Outer Drive Tire Condition	See Notes
Right Outer Drive Tire Brand	Roadmaster
Right Outer Drive Tire Size	225/70R19.5
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 7,275 lbs / R: 13,660 lbs
Transmission Information	Could Not Be Located
Engine Information	5.2L Isuzu In-Line I1B - 4HK1TC

Visible Damages

Wiper Blade	The front left wiper blade is torn.
Grab Iron	The rear grab irons are bent.
EMS Warning Lights	The "check engine" is lit on the EMS screen.
Seats Stained	The seats' cushions are stained.
Driver's Seat	The seat has small holes in the bottom cushion.
Cab Interior	The cab interior is dirty and there are stains on the rubber material under the seats.
Floor Mat	The rubber floor mat is torn.
Front Bumper	The front left bumper is damaged.
Coolant	The coolant is low in the reservoir.
Engine Oil	The engine oil is dark in color.
Frame Rails	The frame rails are rusty.
Air Cooler Tube	The charge air cooler tube is rusty in the engine compartment.
Right Outer Drive Tire	The tire has cuts in the sidewall.
Leaf Springs	The rear left leaf springs are not pilled straight.
Hangers	The leaf spring hangers are rusty.
Rubber Bumpers	The rear rubber bumpers are missing.
Reflective Tape	The reflective tape on the rear of the unit is missing and scratched off.
Ramp	The ramp is missing from the rear of the unit.
Rear Bumper	An aftermarket bumper has been installed onto this unit.
Pull Rope	The rear door's pull rope is damaged.

Aspen Field Services



Front Left / 08-15-2023



Front Right / 08-15-2023

Aspen Field Services



Rear Left / 08-15-2023



Left / 08-15-2023

Aspen Field Services



Front / 08-15-2023



Rear / 08-15-2023

Aspen Field Services



VIN: JALE5W165K7303765 / Axle Information / GVWR: 19,500 lbs / 08-15-2023



Odometer: 133,791 / 08-15-2023

Aspen Field Services



Engine Hours: 5,884 / 08-15-2023



EMS Warning Lights / 08-15-2023

Aspen Field Services



Cab Interior / 08-15-2023



Driver's Seat / 08-15-2023

Aspen Field Services



Passenger's Seat / 08-15-2023



Floorboard / 08-15-2023

Aspen Field Services



Floorboard / 08-15-2023



Pedals / 08-15-2023

Aspen Field Services



Steering Wheel / 08-15-2023



Floorboard / 08-15-2023

Aspen Field Services



Switches and Controls / Radio / A/C / Heated Mirrors / 08-15-2023



Switches and Controls / 08-15-2023

Aspen Field Services



Switches and Controls / 08-15-2023



Switches and Controls / 08-15-2023

Aspen Field Services



Switches and Controls / 08-15-2023



Mirrors / 08-15-2023

Aspen Field Services



Mirrors / 08-15-2023



Steps / 08-15-2023

Aspen Field Services



Handrails / 08-15-2023



Handrails / 08-15-2023

Aspen Field Services



Handrails / 08-15-2023



Handrails / 08-15-2023

Aspen Field Services



Handrails / 08-15-2023



Handrails / 08-15-2023

Aspen Field Services



Steps / 08-15-2023



Box Interior / 08-15-2023

Aspen Field Services



Handrails / 08-15-2023



Handrails / 08-15-2023

Aspen Field Services



Exhaust Pipe / 08-15-2023



Front Lights / 08-15-2023

Aspen Field Services



Front Lights / 08-15-2023



Rear Lights / 08-15-2023

Aspen Field Services



Engine Compartment / 08-15-2023



Engine Compartment / 08-15-2023

Aspen Field Services



Engine Compartment / 08-15-2023



Coolant Level / 08-15-2023

Aspen Field Services



Oil Dipstick / 08-15-2023



Right Steer Tire Condition / 08-15-2023

Aspen Field Services



Right Steer Tire Condition / 08-15-2023



Right Steer Tire Brand / 08-15-2023

Aspen Field Services



Right Steer Tire Size / 08-15-2023



Rear Right Outer Drive Tire Condition / 08-15-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 08-15-2023



Rear Right Outer Drive Tire Brand / 08-15-2023

Aspen Field Services



Rear Right Outer Drive Tire Size / 08-15-2023



Suspension / 08-15-2023

Aspen Field Services



Axles / Suspension / 08-15-2023



Left Steer Tire Condition / 08-15-2023

Aspen Field Services



Left Steer Tire Condition / 08-15-2023



Left Steer Tire Brand / 08-15-2023

Aspen Field Services



Left Steer Tire Size / 08-15-2023



Rear Left Outer Drive Tire Condition / 08-15-2023

Aspen Field Services



Rear Left Outer Drive Tire Condition / 08-15-2023



Rear Left Outer Drive Tire Brand / 08-15-2023

Aspen Field Services



Rear Left Outer Drive Tire Size / 08-15-2023



Suspension / 08-15-2023

Aspen Field Services



Axles / Suspension / 08-15-2023



Axles / Suspension / 08-15-2023

Aspen Field Services



Axles / Suspension / 08-15-2023