



Aspen Field Services

Job #: 58880 /

VIN: 54DB4W1B2LS802618

14' MORGAN DRY VAN BODY, GAS 2020 - ISUZU NPR / LA133371

Specifications

Year	2020
Make	Isuzu
Model	NPR
Date of Inspection	08/16/2023
Location of Inspection	145 Industrial Boulevard, McDonough, GA, 30253
VIN	54DB4W1B2LS802618
GVWR	12,000 lbs
Odometer	53,512
Engine Hours	Could Not Be Located
EMS Warning Lights	Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	See Notes
Passenger's Seat	See Notes
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	See Notes
Steps	No Damages Observed
Handrails	See Notes
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Good Level / Good Color
Coolant Level	Good Level
Suspension	Leaf Spring - No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Cooper
Left Steer Tire Size	LT215/85R16
First Left Outer Drive Tire Condition	No Damages Observed
First Left Outer Drive Tire Brand	Cooper
First Left Outer Drive Tire Size	LT215/85R16
First Left Inner Drive Tire Condition	No Damages Observed

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/87WwnxF3FCsTi2zY>

Notes / Description



Aspen Field Services

Job #: 58880 /

VIN: 54DB4W1B2LS802618

Right Steer Tire Condition	See Notes
Right Steer Tire Brand	Cooper
Right Steer Tire Size	LT215/85R16
First Right Outer Drive Tire Condition	No Damages Observed
First Right Outer Drive Tire Brand	Cooper
First Right Outer Drive Tire Size	LT215/85R16
First Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 4,860 lbs / R: 8,840 lbs
Transmission Information	Could Not Be Located
Engine Information	6.0L GM V-Shaped L96

Visible Damages	
Sheet Metal Panels	The panels on the side of the box are dented.
Active Warnings	The check-engine warning is active on the EMS screen.
Driver's Seat	The bottom seat cushion has stains and the backrest has a small hole.
Passenger's Seat	The bottom seat cushion has stains and the backrest has a small hole.
Cover	The screw access cover is missing from the driver door.
Grab Iron	The rear right grab iron on the box is bent.
Right Steer Tire	The tire is low on air pressure and the outside shoulder is cupping.
Mud Flap	The front left mud flap is missing.
Shocks	The rear shocks are leaking.
Coolers	The coolers seem to be dirty.
Left Mirror	The mirror housing seems to be broken on the side.
Glove Box	The glove box is not staying closed.

Aspen Field Services



Front Left / 08-16-2023



Front Right / 08-16-2023

Aspen Field Services



Rear Left / 08-16-2023



Rear Right / 08-16-2023

Aspen Field Services



Left / 08-16-2023



Right / 08-16-2023

Aspen Field Services




Front / 08-16-2023



Rear / 08-16-2023

Aspen Field Services



VIN: 54DB4W1B2LS802618 / GVWR: 12,000 lbs / Axle Information / 08-16-2023



Odometer: 53,512 / 08-16-2023

Aspen Field Services



EMS Warning Lights / 08-16-2023



Cab Interior / 08-16-2023

Aspen Field Services



Passenger's Seat / 08-16-2023



Driver's Seat / 08-16-2023

Aspen Field Services



Floorboard / 08-16-2023



Floorboard / 08-16-2023

Aspen Field Services



Pedals / 08-16-2023



Steering Wheel / 08-16-2023

Aspen Field Services



Switches and Controls / 08-16-2023



Switches and Controls / 08-17-2023

Aspen Field Services



Switches and Controls / Radio / A/C / 08-16-2023



Switches and Controls / 08-16-2023

Aspen Field Services



Switches and Controls / 08-16-2023



Transmission / 08-17-2023

Aspen Field Services



Steps / 08-16-2023



Handrails / 08-16-2023

Aspen Field Services



Handrails / 08-16-2023



Handrails / 08-16-2023

Aspen Field Services



Mirrors / 08-16-2023



Handrails / 08-16-2023

Aspen Field Services



Handrails / 08-16-2023



Handrails / 08-17-2023

Aspen Field Services



Steps / 08-16-2023



Mirrors / 08-16-2023

Aspen Field Services



Exhaust Pipe / 08-16-2023



Handrails / Steps / 08-16-2023

Aspen Field Services



Box Interior / 08-16-2023



Front Lights / 08-16-2023

Aspen Field Services



Rear Lights / 08-16-2023



Coolant Level / 08-16-2023

Aspen Field Services



Oil Dipstick / 08-17-2023



Engine Compartment / 08-16-2023

Aspen Field Services



Engine Compartment / 08-16-2023



Left Steer Tire Condition / 08-16-2023

Aspen Field Services



Left Steer Tire Condition / 08-16-2023



Left Steer Tire Brand / 08-16-2023

Aspen Field Services



Left Steer Tire Size / 08-16-2023



Axles / Suspension / 08-16-2023

Aspen Field Services



Right Steer Tire Condition / 08-17-2023



Right Steer Tire Condition / 08-16-2023

Aspen Field Services



Right Steer Tire Brand / 08-17-2023



Right Steer Tire Size / 08-16-2023

Aspen Field Services



Axles / Suspension / 08-16-2023



Rear Left Outer Drive Tire Condition / 08-16-2023

Aspen Field Services



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / Suspension /
08-16-2023



Rear Left Outer Drive Tire Brand / 08-16-2023

Aspen Field Services



Rear Left Outer Drive Tire Size / 08-16-2023



Axles / Suspension / 08-16-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / 08-16-2023



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / Suspension / 08-16-2023

Aspen Field Services



Rear Right Outer Drive Tire Brand / 08-17-2023



Rear Right Outer Drive Tire Size / 08-17-2023

Aspen Field Services



Axles / Suspension / 08-16-2023