

2014 ISUZU NPR-HD DIESEL WITH 18' DRY VAN BODY WITH MAXON LIFTGATE. / N/A

Year 2	2014
Make Is	suzu
	NPR-HD Diesel with 18' Dry Van Body with Maxon Liftgate
Date of Inspection 0	08/07/2023
	1500 North America Drive, West Seneca, NY, 14224, USA
VIN	JALC4W161E7002800
GVWR 1	14,500 lbs
Odometer S	See Notes
Engine Hours S	See Notes
EMS Warning Lights S	See Notes
Cab Interior N	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type A	Automatic
Pedals N	No Damages Observed
Floorboard N	No Damages Observed
Radio Y	Yes
A/C Y	Yes
Switches and Controls	No Damages Observed
Power Mirrors N	No
Heated Mirrors N	No
Steering Wheel	No Damages Observed
Mirrors N	No Damages Observed
Steps N	No Damages Observed
Handrails N	No Damages Observed
Exhaust Pipe N	No Damages Observed
Engine Compartment N	No Damages Observed
Engine Serial Plate C	Obstructed
Oil Dipstick	Dark Color / Good Level
Coolant Level L	Low Level
Suspension N	No Damages Observed
Axles N	No Damages Observed
Front Lights S	See Notes
Rear Lights S	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand F	Pathfider
Left Steer Tire Size L	_T215/85R16
Left Outer Drive Tire S Condition	See Notes
Left Outer Drive Tire Brand E	Bridgestone



Video Inspection Link

https://app.aspenfieldservices.com/jobs/video/ykNgBoubrDPACtLqa

Notes / Description

The unit was not operational so the odometer, engine hours, EMS warning lights and the full operational video could not be captured. The lights' condition could not be determined due to the unit not being operational.



Aspen Field Services Job #: 58405 / VIN: JALC4W161E7002800

Left Outer Drive Tire Size	LT215/85R16
Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Pathfider
Right Steer Tire Size	LT215/85R16
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	Yokohama
Right Outer Drive Tire Size	LT215/85R16
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	F: 5,360 LB / R: 9,880 LB
Transmission Information	Obstructed
Engine Information	Obstructed

Visible Damages	
Grille	The front left of the grille is broken.
Batteries	The batteries were dead during the inspection.
Rubber Bumpers	The rear rubber bumpers are damaged on the top.
Sheet Metal Panels	The sheet metal on the right side of the box is dented and the left side is patched.
Column Cover	The steering column plastic covers are coming apart.
Center Panel	The panel cover on the lower dash is coming off.
Rubber Seal	The rubber seal is worn through on the cab near the door.
Coolant	The coolant is low in the reservoir.
Engine Oil Fill Cap	The engine oil fill cap is leaking.
Engine Oil	The oil is dark in color.
Shocks	The front shock is leaking.
Left Outer Drive Tire	The left outer drive tire is cupped on the shoulders.
Front Wheels	Both front whees are rusty. The left outer drive wheel is rusty and the paint is peeling off.
Brake Line	The front left brake line end is corroded.



Front Right / 08-07-2023










199999 Pedals / 08-07-2023












Rear Lights / 08-07-2023





Engine Compartment / Coolant / 08-07-2023









Left Steer Tire Condition / 08-07-2023



Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 08-07-2023





Right Inner Drive Tire Condition / Right Outer Drive Tire Condition / 08-07-2023



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 08-07-2023





Left Inner Drive Tire Condition / Left Outer Drive Tire Condition / 08-07-2023

