

VEHICLE HEALTH REPORT

ISUZU
TRUCK



VIN JALE5W160K7305911
Distance traveled 141,293 mile
Report Period 05/09/2022 ~ 06/22/2023
2019 Isuzu N-Series 5.2L 4HK1

Take Action
 Caution
 OK

Summary Of Vehicle Condition



Operation Type: City



Engine



P0172



Transmission



No DTC found



Mountain Driving

Your vehicle doesn't appear to be regularly driven on mountain roads.



Overall DPF regeneration status



The regeneration of your vehicle's DPF has been successful.



Other



Overheat



Overheat Time: 8 Seconds

Summary Of Vehicle Operation



Fuel economy

11.62 mile/gallon



Brake pedal operation

Your vehicle's braking operation falls within the normal range.



Exhaust brake operation

Your exhaust brake could be used to greater efficiency. Refer to your owners' manual on how to properly use the exhaust brake to reduce regular brake wear.



Accelerator pedal operation (acceleration)

Your accelerator pedal is being used in a way that is associated with normal operation.



Optimizing Fuel Economy

Your vehicle has been accelerated moderately. Follow the dotted line in the graph for optimal fuel efficiency.



General Information

Items	Data
VIN	JALE5W160K7305911
Estimated distance traveled	141,293 mile
Date of report	6/22/2023, 11:45:22 AM
Rear body type	Dry Box



1st visit



VHR Period

2nd visit



Date of data acquisition

05/09/2022

06/22/2023

Estimated distance traveled

104,264 mile

141,293 mile



Next Recommended Service Mileage

Timing of recommended maintenance



General



Inspection Date

06/22/2023

Estimated inspection date

10/10/2023

Distance traveled

141,293 mile

Estimated distanced traveled

151,293 mile



Vehicle Operation Classification


This vehicle has been classified as General Usage. This means that normal usage is expected. Continued to perform the normal scheduled maintenance.



Breakdown of engine operation hours

Classification result

City



Idling (5 min or more)	40 %
Congested traffic or slow driving	12 %
City	33 %
Highway	15 %

Total engine run time: 6,868 hrs




Mountain Driving

Your vehicle doesn't appear to be regularly driven on mountain roads.

Extensive driving on mountain roads (anticipated)

No


Distribution of vehicle operating elevations



Overall DPF Regeneration Status


The regeneration of your vehicle's DPF has been successful.

Overall DPF regeneration status



Recent DPF regeneration success rate.

96.10 %



OK

Total	Automatic	Manual
0	0	0
50	49	1
1040	1039	1
1090	1088	2
95.41 %		

Regen Stopped by Vehicle
Regen Stopped by Driver
Complete
Regeneration Requested
Success Rate

1st VHR
0
13
320
333
96.10 %



Brake Pedal Operation

Your vehicle's braking operation falls within the normal range.


OK

Recent sudden braking

36 times

Percentage of vehicle
operation time (%)

100%
80%
60%
40%
20%
0%




Type of braking

Type of braking	1st VHR
Depression of both brake and accelerator pedals during acceleration	7.46%
Normal braking	91.57%
Hard braking	0.90%
Sudden brake operation	0.07%



Deceleration Frequency By Operation Type

Number of Brake Pedal Applications






Exhaust Brake Operation

Your exhaust brake could be used to greater efficiency. Refer to your owners' manual on how to properly use the exhaust brake to reduce regular brake wear.

94050 times




Accelerator Pedal Operation (Acceleration)

Your accelerator pedal is being used in a way that is associated with normal operation.

Frequency of recent sudden acceleration

464 Times




Accelerator Operation	1st VHR
Normal acceleration	99.43%
Hard acceleration	0.54%
Sudden acceleration	0.02%




Optimizing Fuel Economy

Your vehicle has been accelerated moderately. Follow the dotted line in the graph for optimal fuel efficiency.

Illustration



Accelerator level distribution



Dealer Information

ISUZU
TRUCK

FOX ISUZU TRUCK
24630 HATHAWAY STREET
FARMINGTON HILLS, MI 48335

Dealer Contact Name

Contact Phone Number

Contact Email

Next Recommended Service Mileage



Next Recommended
Service Date

10/10/2023

Next Recommended
Service Mileage

151,293 mile

This vehicle has been classified as General Usage. This means that normal usage is expected. Continued to perform the normal scheduled maintenance.



PSMP/Free Oil Change (Contact Your Service Advisor For Details)

Program Name	Type of Service	Remaining Services
--------------	-----------------	--------------------

This VIN does not have any PSMP or Free Oil Changes Associated With It



Campaign Status		
Campaign Number	Description	Status
19V-835	REAR OUTER WHEEL NUT INSPECTION AND TORQUE 19V-835 (V1906)	Closed



Diagnostic Trouble Code Details	
VIN: JALE5W160K7305911	
Module	DTC DTCs have occurred within 2000 miles Click on DTC for Additional Details
 Engine	P0172
 Transmission	
 MIMAMORI/DRM	
 ABS	
 SCR	



TRUCK INSPECTION SHEET

Isuzu Finance
of America, Inc.

Dealership:	Fox Isuzu
City / State:	Farmington Hills / MI
Lease #:	
Vin #:	JALE5W160K7305911

Year:	2019
Make / Model:	Isuzu / NRR

Mileage:	140352
<u>Diesel</u> / Gas:	
Wheelbase:	212"
Color:	white

Start/Run ?	
<u>Yes</u>	No

Brake %	F:	80%
	R:	70%

Fronts Lights:	✓
Rear Lights:	✓
Cab / Box Lights:	✓
Dash Lights:	good

Truck Deidentified:	Y/N
A/C:	Y/N

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET


BODY TYPE:	
Year / Make:	2019 / Morgan
S/N:	MOH00031-001
Length / Width:	24' / 8'
Floor (wood, etc):	wood
Body Door: (roll up, swing):	roll up
Side Door:	Y / (N)

LIFE GATE:		Y / (N)
Make / Model:		
Capacity:		
	If Reefer unit:	none
Make / Model:		
Year :		Engine Hours:

Chargable Items:

Windshield:	
Seat Damage:	seat bases are wrinkled
Interior Parts Missing:	

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET

Body Damage:

Charges

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET

Misc Repair:	Charges

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET

Mechanical Repair	Charges

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET

Ft. Axle

5 /32

7 /32

Tire Tread
XX/32

R. Axle

10 /32

10 /32

11 /32

11 /32

Tire Size:

225/70R14.5

Exterior

Interior

Warning / Light Codes:

Error Codes:

Please fax back to 914-251-0222. Please use additional sheets if necessary



Isuzu Finance
of America, Inc.

TRUCK INSPECTION SHEET

Other:	Charges

Inspection Time
Inspected By
Accepted By (customer)

Health Report Attached?

Yes	No
-----	----

Pictures Attached?

Yes	No
-----	----

Please fax back to 914-251-0222. Please use additional sheets if necessary