

Aspen Field Services Job #: 59653 / VIN: JALC4W169H7000667

#### GENERAL TRUCK BODY 18' VAN BODY WITH PALFINGER ILM-20 RAIL GATE, DIESEL 2017 - ISUZU NPR-HD / LA122243 NATIONAL OFFICE LIQUIDATORS, LLC

Year2017MakeIsuzuModelNPR-HDDate of Inspection08/30/2023Location of Inspection13443 Freeway Dr, Santa Fe Springs, CA, 90670,VINJALC4W169H7000667GVWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNo Damages ObservedMirrorsNo Damages ObservedMirrorsNo Damages ObservedSteering WheelNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorColant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire SizeLT 215/8SR16Rear Left Outer Drive TireSee NotesLeft Steer Tire SizeKrokhamaLeft Steer Tire SizeKrokhamaLeft Steer Tire SizeKrokhamaLeft Outer Drive TireSee Notes	Specifications	
ModelNPR-HDDate of Inspection08/30/2023Location of Inspection13443 Freeway Dr, Santa Fe Springs, CA, 90670,VINJALC4W169H7000667GVWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsYesNoNo Damages ObservedMirrorsNo Damages ObservedSteering WheelNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLeaf Spring - No Damages ObservedAxlessNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/SSR16Rear Left Outer Drive Tire ConditionSee Notes	Year	2017
NatureNoticeDate of Inspection08/30/2023Location of Inspection13443 Freeway Dr, Santa Fe Springs, CA, 90670,VINJALC4W169H7000667GVWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoNoPamages ObservedMirrorsNo Damages ObservedSteering WheelNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire BrandYokohamaLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Make	Isuzu
Location of Inspection13443 Freeway Dr, Santa Fe Springs, CA, 90670,VINJALC4W169H7000667GVWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedEngine CompartmentNo Damages ObservedAxlesNo Damages ObservedEriont LightsNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokoharmaLeft Steer Tire SizeLT 215/8SR16Rear Left Outer Drive Tire ConditionSee Notes	Model	NPR-HD
90670,VINJALC4W169H7000667GVWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedFloorboardNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoNoPanages ObservedSteering WheelNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedExhaust PipeSingle - No Damages ObservedGoolan LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAlesNo Damages ObservedEngine CompartmentNo Damages ObservedGil DipstickGood Level / Good ColorColant LevelNo Damages ObservedArlesNo Damages ObservedFront LightsNo Damages ObservedAklesNo Damages ObservedAklesNo Damages ObservedErf Steer Tire GrandYokoharnaLeft Steer Tire BrandYokoharnaLeft Steer Tire SizeLT 215/85R16Rear Light Outer Drive Tire ConditionSee Notes	Date of Inspection	08/30/2023
GWWR14,500 lbsOdometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedPransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedMirrorsNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Location of Inspection	
Odometer93,497Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedArkesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	VIN	JALC4W169H7000667
Engine Hours3,150Engine Hours3,150EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedPassenger's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	GVWR	14,500 lbs
EMS Warning LightsActive WarningsCab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPetering WheelNo Damages ObservedMirrorsNo Damages ObservedSteering WheelNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Odometer	93,497
Cab InteriorNo Damages ObservedDriver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Engine Hours	3,150
Driver's SeatNo Damages ObservedPassenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedOil DipstickGood Level / Good ColorColant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	EMS Warning Lights	Active Warnings
Passenger's SeatNo Damages ObservedTransmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedArlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Cab Interior	No Damages Observed
Transmission TypeAutomaticPedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedFront LightsNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Driver's Seat	No Damages Observed
PedalsNo Damages ObservedFloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedStepsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Passenger's Seat	No Damages Observed
FloorboardNo Damages ObservedRadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Transmission Type	Automatic
RadioYesA/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Pedals	No Damages Observed
A/CYesSwitches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedArlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Floorboard	No Damages Observed
Switches and ControlsNo Damages ObservedPower MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Radio	Yes
Power MirrorsNoHeated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	A/C	Yes
Heated MirrorsYesSteering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Switches and Controls	No Damages Observed
Steering WheelNo Damages ObservedMirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire GonditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Power Mirrors	No
MirrorsNo Damages ObservedStepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Heated Mirrors	Yes
StepsNo Damages ObservedHandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Steering Wheel	No Damages Observed
HandrailsNo Damages ObservedExhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Mirrors	No Damages Observed
Exhaust PipeSingle - No Damages ObservedEngine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Steps	No Damages Observed
Engine CompartmentNo Damages ObservedOil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Handrails	No Damages Observed
Oil DipstickGood Level / Good ColorCoolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Exhaust Pipe	Single - No Damages Observed
Coolant LevelLow LevelSuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Engine Compartment	No Damages Observed
SuspensionLeaf Spring - No Damages ObservedAxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Oil Dipstick	Good Level / Good Color
AxlesNo Damages ObservedFront LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Coolant Level	Low Level
Front LightsNo Damages ObservedRear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Suspension	Leaf Spring - No Damages Observed
Rear LightsNo Damages ObservedLeft Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Axles	No Damages Observed
Left Steer Tire ConditionSee NotesLeft Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Front Lights	No Damages Observed
Left Steer Tire BrandYokohamaLeft Steer Tire SizeLT 215/85R16Rear Left Outer Drive Tire ConditionSee Notes	Rear Lights	No Damages Observed
Left Steer Tire Size     LT 215/85R16       Rear Left Outer Drive Tire Condition     See Notes	Left Steer Tire Condition	See Notes
Rear Left Outer Drive Tire See Notes Condition	Left Steer Tire Brand	Yokohama
Condition	Left Steer Tire Size	LT 215/85R16
Rear Left Outer Drive Tire Brand Yokohama		See Notes
	Rear Left Outer Drive Tire Brand	Yokohama



#### Video Inspection Link

https://app.aspenfieldservices.com/jobs/video/YehxYGJPWTprwoEig

#### Notes / Description

The Engine Information was obtained from a VIN-Decoding software.



Aspen Field Services
Job #: 59653 / VIN: JALC4W169H7000667


Rear Left Outer Drive Tire Size	LT 215/85R16
Rear Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	See Notes
Right Steer Tire Brand	Yokohama
Right Steer Tire Size	LT 215/85R16
Rear Right Outer Drive Tire Condition	See Notes
Rear Right Outer Drive Tire Brand	Yokohama
Rear Right Outer Drive Tire Size	LT 215/85R16
Rear Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 5,360 lbs / R: 9,880 lbs
Transmission Information	Could Not Be Located
Engine Information	5.2L Isuzu In-Line I1B - 4HK1TC

Visible Damages	
Top Edge	The top edge of the box is dented on the right.
Right Corner	The lower right corner on the box is dented.
Fuel Filter Warning	There is a warning of water separator on the dash for the fuel filter.
Windshield	The glass is cracked.
Coolant	The coolant is low in the reservoir.
Left Steer Tire	The tire is wearing on the outside shoulder.
Right Steer Tire	The tire is wearing on the shoulders.
Rear Right Outer Drive Tire	The tire has a cut on the sidewall.
Rear Left Outer Drive Tire	The tire is low on air pressure.



Front Left / 08-30-2023



















<image><caption>



























Handrails / 08-30-2023
















Exhaust / 08-30-2023













Oil Dipstick / 08-30-2023






Left Steer Tire Condition / 08-30-2023





Left Steer Tire Size / 08-30-2023














Axles / Suspension / 08-30-2023





Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 08-30-2023





Rear Right Outer Drive Tire Brand / 08-30-2023





Rear Left Outer Drive Tire Condition / 08-30-2023





Rear Left Outer Drive Tire Brand / 08-30-2023



