

20' GENERAL TRUCK BODY INC. DRY VAN BODY WITH PALFINGER ILK-22 LIFTGATE, DIESEL 2018 ISUZU NRR - LA125805 / LA125805

Specifications	
Year	2018
Make	Isuzu
Model	NRR
Date of Inspection	09/07/2023
Location of Inspection	909 N. Grand Avenue, Santa Ana, CA, 92701, USA
VIN	JALE5W169J7304352
GVWR	19,500 LB
Odometer	302,101
Engine Hours	7,985
EMS Warning Lights	Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Engine Serial Plate	8983449080
Oil Dipstick	Good Color / Good Level
Coolant Level	Good Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Blackhawk
Left Steer Tire Size	225/70R19.5
Left Outer Drive Tire Condition	See Notes
Left Outer Drive Tire Brand	Blackhawk

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/PYjXHJN2pCxe24eKs>

Notes / Description

The engine's fuel capacity in liters was obtained from a VIN-Decoding software.



Aspen Field Services

Job #: 59825 /

VIN: JALE5W169J7304352

Left Outer Drive Tire Size	225/70R19.5
Left Inner Drive Tire Condition	See Notes
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Blackhawk
Right Steer Tire Size	225/70R19.5
Right Outer Drive Tire Condition	See Notes
Right Outer Drive Tire Brand	Blackhawk
Right Outer Drive Tire Size	225/70R19.5
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	F: 7,275 LBS / R: 13,660 LBS
Transmission Information	RSU
Engine Information	Isuzu 4HK1TC / 210 HP / 5.2L

Visible Damages	
Sheet Metal Panels	The panels are scratched and have dents in them on the box.
Lip Bent	The rear right top lip on the box is bent.
Service Due	The engine oil and filter replacement warnings are active.
Floor Mat	The floor mat is torn and worn.
Door Rubber Strip	The rubber strip is falling off around the bottom of the right door.
Right Outer Drive Tire	The tire has a gouge in the tread.
Left Drive Tires	Both tires' treads seem to be worn.
Shocks	The front shocks are leaking.
Rear Left Bumper	The bumper is missing a plastic end cap.
Engine Belts	The belts are squeaking.
Warning Light	The left warning light on the lift gate platform is damaged and not working.

Aspen Field Services



Front Left / 09-07-2023



Front / 09-07-2023

Aspen Field Services



Front Right / 09-07-2023



Left / 09-07-2023

Aspen Field Services



Rear Left / 09-07-2023



Rear / 09-07-2023

Aspen Field Services



Rear Right / 09-07-2023



Right / 09-07-2023

Aspen Field Services



VIN: JALE5W169J7304352 / GVWR: 19,500 LB / Axle Information / 09-07-2023



EMS Warning Lights / 09-07-2023

Aspen Field Services



Odometer: 302,101 / 09-07-2023



Engine Hours: 7,985 / 09-07-2023

Aspen Field Services



Passenger's Seat / 09-07-2023



Transmission / 09-07-2023

Aspen Field Services



Pedals / 09-07-2023



Floorboard / 09-07-2023

Aspen Field Services



Floorboard / 09-07-2023



Radio / A/C / 09-07-2023

Aspen Field Services



Switches and Controls / 09-07-2023



Switches and Controls / 09-07-2023

Aspen Field Services



Steering Wheel / 09-07-2023



Mirrors / Handrails / 09-07-2023

Aspen Field Services



Mirrors / 09-07-2023



Steps / 09-07-2023

Aspen Field Services



Handrails / 09-07-2023



Handrails / 09-07-2023

Aspen Field Services



Cab Interior / 09-07-2023



Driver's Seat / 09-07-2023

Aspen Field Services




Handrails / 09-07-2023



Handrails / 09-07-2023

Aspen Field Services



Transmission Information / 09-07-2023



Steps / 09-07-2023

Aspen Field Services



Exhaust Pipe / 09-07-2023



Rear Lights / 09-07-2023

Aspen Field Services



Rear Lights / 09-07-2023



Front Lights / 09-07-2023

Aspen Field Services



Front Lights / 09-07-2023




Engine Compartment / 09-07-2023

Aspen Field Services



Oil Dipstick / 09-07-2023




Engine Compartment / 09-07-2023

Aspen Field Services



Coolant Level / 09-07-2023



Engine Serial Plate: 8983449080 / Engine Information / 09-07-2023

Aspen Field Services



Right Steer Tire Condition / 09-07-2023



Right Steer Tire Brand / 09-07-2023

Aspen Field Services



Right Steer Tire Size / 09-07-2023



Right Steer Tire Condition / 09-07-2023

Aspen Field Services



Suspension / Axles / 09-07-2023



Left Steer Tire Condition / 09-07-2023

Aspen Field Services



Left Steer Tire Brand / 09-07-2023



Left Steer Tire Size / 09-07-2023

Aspen Field Services



Left Steer Tire Condition / 09-07-2023



Suspension / Axles / 09-07-2023

Aspen Field Services



Left Outer Drive Tire Condition / 09-07-2023



Left Outer Drive Tire Brand / 09-07-2023

Aspen Field Services



Left Outer Drive Tire Size / 09-07-2023



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 09-07-2023

Aspen Field Services



Suspension / Axles / 09-07-2023



Right Outer Drive Tire Condition / 09-07-2023

Aspen Field Services



Right Outer Drive Tire Brand / 09-07-2023



Right Outer Drive Tire Size / 09-07-2023

Aspen Field Services



Right Inner Drive Tire Condition / Right Outer Drive Tire Condition / 09-07-2023



Suspension / Axles / 09-07-2023