



Aspen Field Services

Job #: 60453 /

VIN: JALC4W165L7010993

16' MORGAN DRY VAN BODY, DIESEL 2020 - ISUZU NPR-HD / LA130166

Specifications

Year	2020
Make	ISUZU
Model	NPR-HD
Date of Inspection	09/19/2023
Location of Inspection	268 Park St, West Springfield, MA, 01090
VIN	JALC4W165L7010993
GVWR	14,500 lbs
Odometer	56,253
Engine Hours	5,244
EMS Warning Lights	No Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	See Notes
Passenger's Seat	See Notes
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Good Level / Good Color
Coolant Level	Good Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	See Notes
Rear Lights	See Notes
Cylinders	N/A
Left Steer Tire Condition	See Notes
Left Steer Tire Brand	Firestone
Left Steer Tire Size	LT215/85R16
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Goodyear
Left Outer Drive Tire Size	LT215/85R16
Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	No Damages Observed

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/YqiCt5zEeHtTGNftj>

Notes / Description

The engine information was acquired from <https://driving-tests.org/vin-decoder/>



Aspen Field Services

Job #: 60453 /

VIN: JALC4W165L7010993

Right Steer Tire Brand	Firestone
Right Steer Tire Size	LT215/85R16
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	Firestone
Right Outer Drive Tire Size	LT215/85R16
Right Inner Drive Tire Condition	No Damages Observed
Axle information	Front: 5,360 lbs / Rear: 9,880 lbs
Transmission Information	Could Not Be Located
Engine Information	Isuzu 5.2L In-Line 4HK1-TC / 210 HP

Visible Damages	
Driver's Door	The driver's door is dented.
Clearance Light	The top left clearance light lens is missing.
Sheet Metal Panels	The panels on the truck box are scratched and some have dents.
Driver's Seat	The bottom seat cushion has a hole in the material.
Passenger's Seat	The seats are stained.
Interior	The interior is dirty.
Rubber Floor Mat	The rubber floor mat is worn through on the driver side..
Engine Oil	The engine oil and filter need to be changed.
Tail light	The rear right tail light bezel is cracked.
Wheel	The rear right outer wheel is bent on the lip.
Left Steer Tire	The tire is worn on the inside shoulder.
Rear Bumper	The rear bumper is rusty.
Front Right Corner	The corner of the box has a small dent.

Aspen Field Services



Front Left / 09-19-2023



Front / 09-19-2023

Aspen Field Services



Front Right / 09-19-2023



Rear Left / 09-19-2023

Aspen Field Services



Rear / 09-19-2023



Rear Right / 09-19-2023

Aspen Field Services




Left / 09-19-2023




Right / 09-19-2023

Aspen Field Services



VIN: JALC4W165L7010993 / 09-19-2023



GVWR: 14,500 lbs / Axle Information / 09-19-2023

Aspen Field Services



Cab Interior / 09-19-2023



Steps / 09-19-2023

Aspen Field Services



Handrails / 09-19-2023



Driver's Seat / 09-19-2023

Aspen Field Services



Passenger's Seat / 09-19-2023



Steps / 09-19-2023

Aspen Field Services



Handrails / 09-19-2023



Floorboard / 09-19-2023

Aspen Field Services



Floorboard / 09-19-2023



Pedals / 09-19-2023

Aspen Field Services



Steering Wheel / 09-19-2023



Switches and Controls / Radio / A/C / 09-19-2023

Aspen Field Services



Switches and Controls / 09-19-2023



Switches and Controls / 09-19-2023

Aspen Field Services



Switches and Controls / 09-19-2023



Switches and Controls / 09-19-2023

Aspen Field Services



Transmission Type / 09-19-2023



Switches and Controls / 09-19-2023

Aspen Field Services



Handrails / 09-19-2023



Handrails / 09-19-2023

Aspen Field Services



Odometer: 56,253 / 09-19-2023



EMS Warning Lights / 09-19-2023

Aspen Field Services



Engine Hours: 5,244 / 09-19-2023



Front Lights / 09-19-2023

Aspen Field Services



Rear Lights / 09-19-2023



Rear Lights / 09-19-2023

Aspen Field Services



Mirrors / 09-19-2023



Mirrors / 09-19-2023

Aspen Field Services



Handrails / 09-19-2023



Handrails / 09-19-2023

Aspen Field Services



Left Steer Tire Condition / 09-19-2023



Left Steer Tire Brand / 09-19-2023

Aspen Field Services



Left Steer Tire Size / 09-19-2023



Left Outer Drive Tire Condition / 09-19-2023

Aspen Field Services



Left Outer Drive Tire Brand / 09-20-2023



Left Outer Drive Tire Size / 09-19-2023

Aspen Field Services



Left Inner Drive Tire Condition / Suspension / 09-19-2023



Right Steer Tire Condition / 09-19-2023

Aspen Field Services



Right Steer Tire Brand / 09-19-2023



Right Steer Tire Size / 09-19-2023

Aspen Field Services



Right Outer Drive Tire Condition / Suspension / 09-19-2023



Right Outer Drive Tire Brand / 09-19-2023

Aspen Field Services



Right Outer Drive Tire Size / 09-19-2023



Right Inner Drive Tire Condition / Suspension / 09-19-2023

Aspen Field Services



Box / 09-19-2023



Box / 09-19-2023

Aspen Field Services



Exhaust Pipe / 09-19-2023



Axles / Suspension / 09-19-2023

Aspen Field Services



Axles / Suspension / 09-19-2023



Engine Compartment / 09-19-2023

Aspen Field Services



Engine Compartment / 09-19-2023



Coolant level / 09-19-2023

Aspen Field Services



Oil Dipstick / 09-19-2023



Engine Information / 09-19-2023