

# 16' VAN BODY, GAS 2020 ISUZU NPR-HD (LA137591) / LA137591

## Specifications

Year	2020
Make	Isuzu
Model	NPR-HD
Date of Inspection	08/30/2023
Location of Inspection	15 E Industrial Rd, Branford, CT, 06405
VIN	54DC4W1DXLS208865
GVWR	14,500 lbs
Odometer	15,874
Engine Hours	See Notes
EMS Warning Lights	See Notes
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	See Notes
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Low Level / Good Color
Coolant Level	Low Level
Suspension	Leaf Spring - No Damages Observed
Axles	No Damages Observed
Front Lights	See Notes
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Goodyear
Left Steer Tire Size	225/70R19.5
Rear Left Outer Drive Tire Condition	No Damages Observed
Rear Left Outer Drive Tire Brand	Goodyear
Rear Left Outer Drive Tire Size	225/70R19.5
Rear Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Goodyear

## Equipment Photo



## Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/4mFckTWK5bM9kQA4T>

## Notes / Description

The unit was left with a missing catalytic converter and a rag in place of a coolant cap. Therefore, the truck was not started during the time of the inspection, in order to avoid further damage to the engine. The Engine Information was obtained from a VIN-Decoding software.



## Aspen Field Services

Job #: 59439 /

VIN: 54DC4W1DXLS208865

Right Steer Tire Size	225/70R19.5
Rear Right Outer Drive Tire Condition	No Damages Observed
Rear Right Outer Drive Tire Brand	Goodyear
Rear Right Outer Drive Tire Size	225/70R19.5
Rear Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 6,630 lbs / R: 11,020 lbs
Transmission Information	Could Not Be Located
Engine Information	6.6L GM V-Shaped L8T

### Visible Damages

Catalytic Converters	Both of the catalytic converters are missing.
Mirror	The right mirror is cracked.
Plywood	The plywood panels in the box are damaged on the bottom.
Sheet Metal Panels	A couple of the metal panels on the front of the box are bent behind the cab.
Coolant Cap	The cap is missing.
Coolant	The coolant is low in the reservoir.
Engine Oil	The oil level on the dipstick is low.
Rear Right Platform	The aluminum strip is bent under the rear platform.

# Aspen Field Services



Front Left / 08-30-2023



Front Right / 08-30-2023



# Aspen Field Services



Rear Right / 08-30-2023



Front / Front Lights / 08-30-2023



# Aspen Field Services



Rear / 08-30-2023



VIN: 54DC4W1DXLS208865 / GVWR: 14,500 lbs / Axle Information / 08-30-2023

# Aspen Field Services



Odometer: 15,874 / 08-30-2023



Cab Interior / 08-30-2023



## Aspen Field Services



Floorboard / 08-30-2023



Pedals / 08-30-2023



# Aspen Field Services



Driver's Seat / 08-30-2023



Steering Wheel / 08-30-2023



# Aspen Field Services



Switches and Controls / 08-30-2023



Switches and Controls / 08-30-2023



# Aspen Field Services



Switches and Controls / Radio / A/C / Heated Mirrors / 08-30-2023



Transmission / 08-30-2023



# Aspen Field Services



Floorboard / 08-30-2023



Passenger's Seat / 08-30-2023



# Aspen Field Services



Steps / 08-30-2023



Handrails / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Handrails / 08-30-2023



# Aspen Field Services



Mirrors / 08-30-2023



Steps / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Handrails / 08-30-2023

# Aspen Field Services



Mirrors / 08-30-2023



Handrails / 08-30-2023



## Aspen Field Services



Exhaust Pipe / 08-30-2023



Handrails / 08-30-2023

# Aspen Field Services



Handrails / 08-30-2023



Box Interior / 08-30-2023



# Aspen Field Services



Rear Lights / 08-30-2023



Rear Lights / 08-30-2023



# Aspen Field Services



Engine Compartment / 08-30-2023



Engine Compartment / 08-30-2023



# Aspen Field Services



Coolant Level / 08-30-2023



Oil Dipstick / 08-30-2023



# Aspen Field Services



Right Steer Tire Condition / 08-30-2023



Right Steer Tire Condition / 08-30-2023



# Aspen Field Services



Right Steer Tire Brand / 08-30-2023



Right Steer Tire Size / 08-30-2023



# Aspen Field Services



Axles / Suspension / 08-30-2023



Left Steer Tire Condition / 08-30-2023



# Aspen Field Services



Left Steer Tire Condition / 08-30-2023



Left Steer Tire Brand / 08-30-2023



# Aspen Field Services



Left Steer Tire Size / 08-30-2023



Axles / Suspension / 08-30-2023



# Aspen Field Services



Rear Left Outer Drive Tire Condition / 08-30-2023



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 08-30-2023



# Aspen Field Services



Rear Left Outer Drive Tire Brand / 08-30-2023



Rear Left Outer Drive Tire Size / 08-30-2023



## Aspen Field Services



Axles / Suspension / 08-30-2023



Rear Right Outer Drive Tire Condition / 08-30-2023



# Aspen Field Services



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 08-30-2023



Rear Right Outer Drive Tire Brand / 08-30-2023



## Aspen Field Services



Rear Right Outer Drive Tire Size / 08-30-2023



Axles / Suspension / 08-30-2023