











Inspection Detail				
Client:	Isuzu Finance			
Inspected by:	Richard V. White			
Location of Inspection:	4950 Keller Springs Rd Suite 190, Addison, TX 75001, USA			
Phone No / Email:	+1 405 426 2381 / tgermain@asihealthservices.com			
Date of Inspection:	1/6/2025 Job#: 868bpkvap			
Year:	2020	Make:	Isuzu	
Model:	NPR-HD	VIN:	JALC4W161L7013261	



Inspection Details

Unit Information					
GVWR:	14,500 Lbs	Odometer:	140,988	Engine Hours:	3,412
EMS Warning Lights:	No				

Interior Details					
Cab Interior:	See Notes	Driver's Seat:	No Damages Observed	Passenger's Seat:	No Damages Observed
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed
Power Mirrors:	No	Heated Mirrors:	Yes	Steering Wheel:	No Damages Observed
Cab Mirror:	N/A	Box Condition:	N/A		

Exterior Details					
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed
Suspension:	No Damages Observed	Axles:	No Damages Observed		

Engine Details					
Engine Compartment:	No Damages Observed	Oil Dipstick:	Low Level / Dark in Color	Coolant Level:	Low Level
Engine Serial Plate:	Obstructed				

Observations / Comments

The site contact present during the inspection, Travis Germain, confirmed that the horn, reverse lights, and back-up alarm are all operational.



	Tires Details				
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	Hercules Tires	First Left Steer Tire Size:	215/85R16
First Right Steer Steer Tire Condition:	No Damages Observed	First Right Steer Steer Tire Brand:	Hercules Tires	First Right Steer Steer Tire Size:	215/85R16
First Left Outer Drive Tire Condition:	No Damages Observed	First Left Outer Drive Tire Brand:	Goodyear	First Left Outer Drive Tire Size:	215/85R16
First Left Inner Drive Tire Condition:	No Damages Observed	First Left Inner Drive Tire Brand:	Goodyear	First Left Inner Drive Tire Size:	215/85R16
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	Goodyear	First Right Outer Drive Tire Size:	215/85R16
First Right Inner Drive Tire Condition:	No Damages Observed	First Right Inner Drive Tire Brand:	Goodyear	First Right Inner Drive Tire Size:	215/85R16



Repair Items				
Item Name	Item Labor Cost	Item Part Cost	Total Cost	
Windshield	\$150.00	\$800.00	\$950.00	
	\$950.00			



Wear and Tear Items			
Item Name	Item Comments		
Grease Cap Cover	The front right steer axle end cap cover appears to be leaking, and the hub is oily around the cover.		
Coolant	The coolant appears to be below the maximum level in the reservoir.		
Engine Oil	The engine oil is dark in color and at a low level on the dipstick.		
Windshield	The windshield has a crack in the glass.		













































































































































































































































