











inspection Detail				
Client:	Isuzu Finance			
Inspected by:	Yvette Gerardo			
Location of Inspection:	1233 E Camelback Rd, Phoenix, AZ 85014, USA			
Phone No / Email:	+1 602 798 2939 / arivera@Courtesyauto.com			
Date of Inspection:	3/17/2025 Job#: 868d132w5			
Year:	2020 Make: Isuzu			
Model:	NPR-HD VIN: 54DC4W1D4LS207713			



Inspection Details

Unit Information					
GVWR: 14,500 Lbs Odometer: 30,972 Engine Hours: See Notes				See Notes	
EMS Warning Lights:	No				

Interior Details					
Cab Interior:	See Notes	Driver's Seat:	See Notes	Passenger's Seat:	No Damages Observed
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed
Power Mirrors:	No	Heated Mirrors:	No	Steering Wheel:	No Damages Observed
Cab Mirror:	N/A	Box Condition:	See Notes		

Exterior Details					
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed
Suspension:	No Damages Observed	Axles:	No Damages Observed		

Engine Details					
Engine Compartment:	See Notes	Oil Dipstick:	Good Level / Good Color	Coolant Level:	See Notes
Engine Serial Plate:	Obstructed				

Observations / Comments

The unit runs and drives.



Tires Details					
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	Good Year	First Left Steer Tire Size:	225/70R19.5
First Right Steer Steer Tire Condition:	No Damages Observed	First Right Steer Steer Tire Brand:	Good Year	First Right Steer Steer Tire Size:	225/70R19.5
First Left Outer Drive Tire Condition:	No Damages Observed	First Left Outer Drive Tire Brand:	Good Year	First Left Outer Drive Tire Size:	225/70R19.5
First Left Inner Drive Tire Condition:	No Damages Observed	First Left Inner Drive Tire Brand:	Good Year	First Left Inner Drive Tire Size:	225/70R19.5
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	Good Year	First Right Outer Drive Tire Size:	225/70R19.5
First Right Inner Drive Tire Condition:	No Damages Observed	First Right Inner Drive Tire Brand:	Good Year	First Right Inner Drive Tire Size:	225/70R19.5



Repair Items					
Item Name Item Labor Cost Item Part Cost Total Cost					
Engine Bay Leaks	\$600.00	\$500.00	\$1,100.00		
Driver's Seat	\$150.00	\$450.00	\$600.00		
Corner Cover	\$300.00	\$250.00	\$550.00		
	\$2,250.00				



Wear and Tear Items				
Item Name	Item Comments			
Engine Bay Leaks	The front left frame rail is oily, and there may be a leak in the engine bay. The exact location of the leak is unclear and will require further diagnostics.			
Brake Line	The metal brake line on the front right appears to be oily and may be leaking.			
Coolant	The coolant reservoir appears to be empty.			
Oil Fill Cap	The valve cover is oily around the oil fill cap area, and the cap may be leaking.			
Fuse Panel Cover	The panel cover appears to have been removed and is lying on the floor.			
Driver's Seat	The backrest material appears to be ripped at the bottom right corner, and the bottom cushion material is stained.			
Corner Cover	The front-right corner cover of the box has dents.			













































































































































































































































































