











Inspection Detail				
Client:	Isuzu Finance			
Inspected by:	Terri Candler			
Location of Inspection:	2323 W Bell Rd, Phoenix, AZ 85023, USA			
Phone No / Email:	+1 405 426 2381 / TFraser@vtaig.com			
Date of Inspection:	5/28/2025 Job#: 868e0930u			
Year:	2024	Make:	CHEVROLET	
Model:	Silverado	VIN / SN:	1GCPABEK6RZ329165	



Inspection Details

Unit Information							
GVWR:	6,800	Odometer:	8,682	Engine Hours:	294	EMS Warning Lights:	No

Interior Details					
Interior:	No Damages Observed	Driver's Seat:	No Damages Observed	Passenger's Seat:	No Damages Observed
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed
Power Mirrors:	Yes	Heated Mirrors:	Yes	Steering Wheel:	No Damages Observed
Cab Minnan	No Domono Obromo d			,	,

Cab Mirror: No Damages Observed

Exterior Details					
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed
Suspension:	No Damages Observed	Axles:	No Damages Observed		

Engine Details					
Engine Compartment:	No Damages Observed	Oil Dipstick:	Good Level / Good Color	Coolant Level:	Good Level

Observations / Comments

The unit runs and drives. The unit is in excellent condition with low mileage.

Disclaimer



Tires Details					
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	General	First Left Steer Tire Size:	275/60R20
First Right Steer Tire Condition:	No Damages Observed	First Right Steer Tire Brand:	General	First Right Steer Tire Size:	275/60R20
First Left Outer Drive Tire Condition:	No Damages Observed	First Left Outer Drive Tire Brand:	General	First Left Outer Drive Tire Size:	275/60R20
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	General	First Right Outer Drive Tire Size:	275/60R20



Wear and Tear Items			
Item Name	Item Comments		
Interior Cleaning	The unit is in excellent condition and only requires cleaning.		
Fuel	The fuel is below 50%.		































































































































































































