




Inspection Detail			
	<b>Client:</b>	Isuzu Finance	
	<b>Inspected by:</b>		
	<b>Location of Inspection:</b>	2425 Broadway St NE, Minneapolis, MN 55413, USA	
	<b>Phone No / Email:</b>	+1 612 616 2017 / curran.maguire@transwest.com	
	<b>Date of Inspection:</b>	6/13/2025	<b>Job#:</b> 868e9u9rz
	<b>Year:</b>	2020	<b>Make:</b> ISUZU
	<b>Model:</b>	NPR-HD	<b>VIN:</b> 54DC4W1B8LS801655

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Inspection Details****Unit Information**

<b>GVWR:</b>	14,500	<b>Odometer:</b>	107,855	<b>Engine Hours:</b>	See Notes
<b>EMS Warning Lights:</b>	No				

**Interior Details**

<b>Cab Interior:</b>	No Damages Observed	<b>Driver's Seat:</b>	No Damages Observed	<b>Passenger's Seat:</b>	No Damages Observed
<b>Transmission Type:</b>	Automatic	<b>Pedals:</b>	No Damages Observed	<b>Floorboard:</b>	No Damages Observed
<b>Radio:</b>	Yes	<b>A/C:</b>	Yes	<b>Switches and Controls:</b>	No Damages Observed
<b>Power Mirrors:</b>	No	<b>Heated Mirrors:</b>	No	<b>Steering Wheel:</b>	No Damages Observed
<b>Cab Mirror:</b>	N/A	<b>Box Condition:</b>	No Damages observed		

**Exterior Details**

<b>Mirrors:</b>	No Damages Observed	<b>Steps:</b>	See Notes	<b>Handrails:</b>	No Damages Observed
<b>Exhaust System:</b>	See Notes	<b>Front Lights:</b>	See Notes	<b>Rear Lights:</b>	No Damages Observed
<b>Suspension:</b>	See Notes	<b>Axles:</b>	No Damages Observed		

**Engine Details**

<b>Engine Compartment:</b>	No Damages Observed	<b>Oil Dipstick:</b>	Good Level / Dark in Color	<b>Coolant Level:</b>	Low Level
<b>Engine Serial Plate:</b>	Obstructed				

**Observations / Comments**

The unit runs and drives. The unit does not display engine hours.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tires Details					
<b>First Left Steer Tire Condition:</b>	No Damages Observed	<b>First Left Steer Tire Brand:</b>	Hercules	<b>First Left Steer Tire Size:</b>	225/70R19.5
<b>First Right Steer Tire Condition:</b>	No Damages Observed	<b>First Right Steer Tire Brand:</b>	Hercules	<b>First Right Steer Tire Size:</b>	225/70R19.5
<b>First Left Outer Drive Tire Condition:</b>	No Damages Observed	<b>First Left Outer Drive Tire Brand:</b>	Hercules	<b>First Left Outer Drive Tire Size:</b>	225/70R19.5
<b>First Left Inner Drive Tire Condition:</b>	No Damages Observed	<b>First Left Inner Drive Tire Brand:</b>	Hercules	<b>First Left Inner Drive Tire Size:</b>	225/70R19.5
<b>First Right Outer Drive Tire Condition:</b>	No Damages Observed	<b>First Right Outer Drive Tire Brand:</b>	Hercules	<b>First Right Outer Drive Tire Size:</b>	225/70R19.5
<b>First Right Inner Drive Tire Condition:</b>	No Damages Observed	<b>First Right Inner Drive Tire Brand:</b>	Hercules	<b>First Right Inner Drive Tire Size:</b>	225/70R19.5

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Repair Items			
Item Name	Item Labor Cost	Item Part Cost	Total Cost
Rust Damage	\$300.00	\$450.00	\$750.00
Paint	\$450.00	\$250.00	\$700.00
Total Repairs:			\$1,450.00

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



Wear and Tear Items	
Item Name	Item Comments
Rust Damage	There is rust on the frame, rear Mansfield bar, and exhaust. The rust is slowly peeling the paint on the frame.
Front Ball Joints	The front steering ball joints are worn and can be replaced.
Oil Change	The oil is dark and should be replaced.
Coolant Low	The coolant level is low and needs to be refilled.
Drivers Side Steps	The driver's side plastic steps are broken and can be replaced.
Paint	The paint on the Mansfield bar and the frame has succumbed to rust, and the unit can be repainted.
Interior Dirty	The interior is dirty and has residue from a spilled drink that needs to be cleaned.
Turn Signals	The turn signals were not used in the operational video and may be inoperational.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Left****Front Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear Left****Rear Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Front****Rear****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Left****Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



UNITED STATES / ETATS-UNIS 06/2020  
THIS VEHICLE IS AN INCOMPLETE  
VEHICLE./LE VEHICULE EST UN  
VEHICULE INCOMPLET.  
GVWR/PNBV: 6,577 KG (14,500 LB)  
GAWR/PNBE: 3,007 KG (6,630 LB)  
(FRONT/AV.) 225/70R19.5F/G TIRES/PNEU  
19.5X6.00 RIMS/JANTE  
590KPA(85PSI), COLD TIRE  
PRESSURE/PRESSION A FROID  
GAWR/PNBE: 4,998 KG (11,020 LB)  
(REAR/ARR.) 225/70R19.5F/G TIRES/PNEU  
19.5X6.00 RIMS/JANTE  
590KPA(85PSI), COLD TIRE  
PRESSURE/PRESSION A FROID  
DUAL/DOUBLE  
GVWR/PNBV: 9,299KG(20,500LB)  
VIN: 54DC4W1B8LS801655  
TYPE: TRU/CAM

VEHICLE EMISSION CONTROL INFORMATION  
/INFORMATION DE CONTRÔLE DES ÉMISSIONS DE VÉHICULES

THIS VEHICLE COMPLIES WITH U.S. EPA AND CALIFORNIA  
REGULATIONS FOR 2020 HEAVY-DUTY VEHICLES.  
/CE VEHICULE EST CONFORME AUX RÈGLEMENTS  
DE L'ÉPA DES ÉTATS-UNIS ET DE LA CALIFORNIE  
RELATIFS AUX VÉHICULES UTILITAIRES LOURDS DE 2020.

VEHICLE FAMILY CODE: L5KX2V0CVLHD  
/CODE DE FAMILLE DE VÉHICULES

REGULATORY SUB CATEGORY  
/SOUIS-CATÉGORIE DE RÉGLEMENTATION

VEHICULAR VEHICLES AT OR BELOW 10,500 POUNDS GVWR  
/VÉHICULES SPÉCIALISÉS DE OU INFÉRIEUR  
À 4,763 KG / 10,500 LB (PNEU)


EMISSION CONTROL IDENTIFIERS  
/IDENTIFICATEURS DE CONTRÔLE DES ÉMISSIONS

[illegible]

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Odometer: 107,855**

**EMS Panel**

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Driver's Seat****Steering Wheel****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Switches and Controls****Switches and Controls****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls / A/C / Radio****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Transmission****Switches and Controls / Handrails****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.


**Switches and Controls / Handrails****Floorboard****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Passenger's Seat****Floorboard / Pedals****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Pedals****Cab Interior****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Front Lights****Rear Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Mirrors**

**Steps**

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Handrails**

**Handrails**

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Mirrors****Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.





**Handrails****Handrails****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Box Condition****Box Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Engine Compartment****Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Coolant Level****Oil Dipstick****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Oil Dipstick****First Left Steer Tire Condition****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Steer Tire Size****First Left Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Steer Tire Brand Condition****Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles / Suspension****First Left Outer Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Outer Drive Tire Brand****First Left Outer Drive Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Outer Drive Tire Condition / First Left Inner Drive Tire Condition****First Left Inner Drive Tire Condition****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles / Suspension****First Right Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Steer Tire Brand****First Right Steer Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Steer Tire Condition****Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Outer Drive Tire Condition****First Right Outer Drive Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Outer Drive Tire Size****First Right Outer Drive Tire Condition / First Right Inner Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Inner Drive Tire Condition****Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles / Suspension****Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Exhaust System****Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.