











Inspection Detail				
Client:	Isuzu Finance			
Inspected by:				
Location of Inspection:	2201 W Bell Rd, Phoenix, AZ 85023, USA			
Phone No / Email:	+1 602 881 9525 / TFraser@vtag.com			
Date of Inspection:	7/24/2025 Job#: 868ew80x4			
Year:	2020	Make:	Isuzu	
Model:	FTR	VIN:	54DK6S164LSG70115	



Inspection Details

Unit Information					
GVWR:	25,950	Odometer:	226,721	Engine Hours:	8,931
EMS Warning Lights:	Yes				

Interior Details					
Cab Interior:	See Notes	Driver's Seat:	See Notes	Passenger's Seat:	See Notes
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed
Power Mirrors:	No	Heated Mirrors:	No	Steering Wheel:	No Damages Observed
Cab Mirror:	N/A	Box Condition:	See Notes		

Exterior Details					
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	See Notes	Rear Lights:	See Notes
Suspension:	No Damages Observed	Axles:	No Damages Observed		

Engine Details					
Engine Compartment:	See Notes	Oil Dipstick:	Good Level / Dark in Color	Coolant Level:	Good Level
Engine Serial Plate:	Obstructed				

Observations / Comments

The unit runs and drives. The odometer was confirmed during the inspection to be 226,721.



Tires Details					
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	Sotera	First Left Steer Tire Size:	255/70R22.5
First Right Steer Steer Tire Condition:	No Damages Observed	First Right Steer Steer Tire Brand:	Sotera	First Right Steer Steer Tire Size:	Obstructed
First Left Outer Drive Tire Condition:	See Notes	First Left Outer Drive Tire Brand:	Sailun	First Left Outer Drive Tire Size:	255/70R22.5
First Left Inner Drive Tire Condition:	See Notes	First Left Inner Drive Tire Brand:	Sailun	First Left Inner Drive Tire Size:	255/70R22.5
First Right Outer Drive Tire Condition:	See Notes	First Right Outer Drive Tire Brand:	Dawg Pound	First Right Outer Drive Tire Size:	255/70R22.5
First Right Inner Drive Tire Condition:	See Notes	First Right Inner Drive Tire Brand:	Dawg Pound	First Right Inner Drive Tire Size:	255/70R22.5



Repair Items				
Item Name	Item Labor Cost	Item Part Cost	Total Cost	
Rear Brakes	\$300.00	\$450.00	\$750.00	
Front Brakes	\$300.00	\$450.00	\$750.00	
Rear Box Door	\$300.00	\$618.00	\$918.00	
Floor Mat	\$300.00	\$340.00	\$640.00	
Check Engine Light	\$450.00	\$1,000.00	\$1,450.00	
Box Front Top Right Corner	\$150.00	\$250.00	\$400.00	
Paint	\$450.00	\$275.00	\$725.00	
Rear Lift Gate	\$450.00	\$5,250.00	\$5,700.00	
Marker Lights	\$450.00	\$792.00	\$1,242.00	
Total Repairs: \$12				



Wear and Tear Items			
Item Name	Item Comments		
Rear Brakes	The rear brakes sounded squeaky each time the unit came to a stop. The unit may need new brake shoes.		
Rear Right Inner Tire	The right inner tire is worn and needs to be replaced.		
Rear Right Outer Tire	The right outer tire is worn and needs to be replaced.		
Rear Left Inner Tire	The left inner tire is worn and needs to be replaced.		
Rear Left Outer Tire	The rear left tire is worn and needs to be replaced.		
Front Brakes	The unit's brakes sounded squeaky each time it came to a stop. The unit may need new brake shoes.		
Missing Rivet	The front left rounded corner of the box is missing the second rivet from the bottom.		
Oil Is Dark	The unit's oil is dark and the unit could use a full service.		
Rear Box Door	The unit's rear van door has a crack in the bottom panel. Other panels are worn, scratched, and dented.		
Front Bumper	The bumper has a small dent on the right side edge in front of the steer tire and can be fixed.		
Driver's Seat	The driver's seat is stained and has a small tear on the bottom cushion and can be repaired.		
Passenger's Seat	The passenger's seat is stained and dirty and can be replaced.		
Floor Mat	The floor mat has a large tear behind the center console and can be replaced.		
Interior Dirty	The unit's interior is coated in old soda residue and other unknown stains on the plastic and floorboard.		
Headliner	The headliner is stained and needs to be cleaned.		
Check Engine Light	The check engine light is on and needs further diagnosis.		
Box Front Top Right Corner	The plastic corner cap that houses a marker light appears damaged and is held in place with duct tape.		
Paint	The paint on the bumper, van sides, and the door is worn and can be repainted.		
Fan Belt	The fan belt sounds like it was slipping in the operational video and may need replacement.		
Rear Lift Gate	The lift gate has a large dent in the center of the main frame and the folding platform. The lift gate still operates.		
Marker Lights	The marker lights on the dry box and the cab clearance lights were not shown operating and may need to be replaced.		



























































































































































































































