











Inspection Detail					
Client:	Isuzu Finance	Isuzu Finance			
Inspected by:	Leonardo Correa	Leonardo Correa			
Location of Inspection:	2323 W Bell Rd, Phoeni:	2323 W Bell Rd, Phoenix, AZ 85023, USA			
Phone No / Email:	+1 601 881 9525 / tfraser@vtaig.com				
Date of Inspection:	11/10/2025 Job#: 868g49vpp				
Year:	2022	Make:	GMC		
Model:	Savana	VIN / SN:	1GTW7AFP3N1220654		



Inspection Deta	ils
-----------------	-----

Unit Information							
GVWR:	8,600	Odometer:	32,620	Engine Hours:	See Notes	EMS Warning Lights:	Yes

Interior Details					
Interior:	No Damages Observed	Driver's Seat:	No Damages Observed	Passenger's Seat:	No Damages Observed
Transmission Type:	Automatic	Pedals:	See Notes	Floorboard:	N/A
Radio:	Yes	A/C:	Yes	Switches and Controls:	See Notes
Power Mirrors:	Yes	Heated Mirrors:	No	Steering Wheel:	No Damages Observed
Cab Mirror	No Domagos Observed				,

Cab Mirror: No Damages Observed

Exterior Details					
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed
Suspension:	No Damages Observed	Axles:	No Damages Observed		

Engine Details					
Engine Compartment:	See Notes	Oil Dipstick:	Low Level / Dark in Color	Coolant Level:	Low Level

Observations / Comments

The unit starts and operates. The unit does not display engine hours.



	Tires Details					
Left Steer Tire Condition:	No Damages Observed	Left Steer Tire Brand:	Bridgestone	Left Steer Tire Size:	245/75R16	
Right Steer Tire Condition:	No Damages Observed	Right Steer Tire Brand:	Bridgestone	Right Steer Tire Size:	245/75R16	
First Left Outer Drive Tire Condition:	No Damages Observed	First Left Outer Drive Tire Brand:	Bridgestone	First Left Outer Drive Tire Size:	245/75R16	
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	Bridgestone	First Right Outer Drive Tire Size:	245/75R16	



Repair Items					
Item Name	Item Labor Cost	Item Part Cost	Total Cost		
Engine Oil Pan	\$300.00	\$250.00	\$550.00		
Windshield	\$150.00	\$800.00	\$950.00		
Total Repairs: \$1,500.					



Wear and Tear Items				
Item Name	Item Comments			
Brake Pedal Cover	The unit's brake pedal cover is peeling away from the pedal.			
Engine Oil Pan	The unit's engine oil pan appears wet and may be leaking, and it will need further diagnostics and repairs.			
Coolant	The unit's coolant needs to be topped off.			
Parking Brake Lever	The unit's parking brake lever is loose and hanging free and will need repairs or replacement.			
Oil Change Light	The unit has an active service reminder on the dash, and the unit's engine oil appears dark. The unit may need a service.			
Windshield	The unit's windshield seal is ripped out on the top part of the unit's front windshield and will need repairs.			

































































































































































































































