











| Inspection Detail | | | | |
|-------------------------|--|------|-------------------|--|
| Client: | Isuzu Finance | | | |
| Inspected by: | | | | |
| Location of Inspection: | 1943 E Palmetto St, Florence, SC 29506, USA | | | |
| Phone No / Email: | +1 843 250 1100 / ChrisH@Bunchtruckgroup.com | | | |
| Date of Inspection: | 12/4/2025 Job#: 868gg7d4g | | | |
| Year: | 2020 Make: Isuzu | | | |
| Model: | NPR-HD | VIN: | 54DC4W1D7LS208533 | |



Inspection Details

| Unit Information | | | | | |
|---------------------|--------|-----------|--------|---------------|-----------|
| GVWR: | 14,500 | Odometer: | 80,910 | Engine Hours: | See Notes |
| EMS Warning Lights: | No | | | | |

| Interior Details | | | | | |
|--------------------|---------------------|-----------------|---------------------|------------------------|---------------------|
| Cab Interior: | See Notes | Driver's Seat: | See Notes | Passenger's Seat: | See Notes |
| Transmission Type: | Automatic | Pedals: | No Damages Observed | Floorboard: | No Damages Observed |
| Radio: | Yes | A/C: | Yes | Switches and Controls: | No Damages Observed |
| Power Mirrors: | No | Heated Mirrors: | No | Steering Wheel: | No Damages Observed |
| Cab Mirror: | No Damages Observed | Box Condition: | See Notes | | |

| Exterior Details | | | | | |
|-------------------------|---------------------|---------------|---------------------|--------------|---------------------|
| Mirrors: | No Damages Observed | Steps: | No Damages Observed | Handrails: | No Damages Observed |
| Exhaust System: | See Notes | Front Lights: | No Damages Observed | Rear Lights: | No Damages Observed |
| Suspension: | No Damages Observed | Axles: | See Notes | | |

| Engine Details | | | | | |
|----------------------|---|--|--|--|------------|
| Engine Compartment: | Engine Compartment: No Damages Observed Oil Dipstick: Good Level / Good Color Coolant Level: Good Level | | | | Good Level |
| Engine Serial Plate: | Obstructed | | | | |

Observations / Comments

The unit starts and operates. The horn is operational. The unit does not display engine hours.



| Tires Details | | | | | |
|--|---------------------|--|------------|---------------------------------------|-------------|
| Left Steer Tire Condition: | No Damages Observed | Left Steer Tire Brand: | Obstructed | Left Steer Tire Size: | 225/70R19.5 |
| Right Steer Tire Condition: | No Damages Observed | Right Steer Tire Brand: | Cooper | Right Steer Tire Size: | 225/70R19.5 |
| First Left Outer Drive Tire Condition: | See Notes | First Left Outer Drive Tire Brand: | Good Year | First Left Outer Drive Tire Size: | 225/70R19.5 |
| First Left Inner Drive Tire Condition: | See Notes | First Left Inner Drive Tire Brand: | Good Year | First Left Inner Drive Tire Size: | 225/70R19.5 |
| First Right Outer Drive Tire Condition: | See Notes | First Right Outer Drive Tire Brand: | Good Year | First Right Outer Drive Tire Size: | 225/70R19.5 |
| First Right Inner Drive Tire Condition: | See Notes | First Right Inner Drive Tire Brand: | Good Year | First Right Inner Drive Tire Size: | 225/70R19.5 |



| Repair Items | | | | | |
|-----------------------|-----------------------|----------------|------------|--|--|
| Item Name | Item Labor Cost | Item Part Cost | Total Cost | | |
| Box Condition | \$150.00 | \$350.00 | \$500.00 | | |
| Rear Bumper | \$150.00 | \$425.00 | \$575.00 | | |
| Passenger's Seat | \$150.00 | \$250.00 | \$400.00 | | |
| Rear Door Seals | \$150.00 | \$560.00 | \$710.00 | | |
| Rear Doors | \$300.00 | \$1,115.00 | \$1,415.00 | | |
| Fuel Tank | \$300.00 | \$1,178.00 | \$1,478.00 | | |
| Rear Axle | \$450.00 | \$80.00 | \$530.00 | | |
| Rear Left Outer Tire | \$150.00 | \$665.00 | \$815.00 | | |
| Rear Left Inner Tire | \$150.00 | \$665.00 | \$815.00 | | |
| Rear Right Inner Tire | \$150.00 | \$665.00 | \$815.00 | | |
| Rear Right Outer Tire | \$150.00 | \$665.00 | \$815.00 | | |
| Wood Strip Chassis | \$900.00 | \$600.00 | \$1,500.00 | | |
| Right Side Panel | \$600.00 | \$600.00 | \$1,200.00 | | |
| | Total Repairs: \$11,5 | | | | |



| Wear and Tear Items | | | |
|------------------------|--|--|--|
| Item Name | Item Comments | | |
| Box Condition | The aluminium panel on the wall has small dents. | | |
| Right Side Panel | The front right bottom panel is dented. | | |
| Exhaust Rubber Support | The rubber support is cracking. | | |
| Wood Strip Chassis | The wood strips under the chassis are cracking and need to be replaced. | | |
| Rear Right Outer Tire | The tire is worn and should be replaced. | | |
| Rear Right Inner Tire | The tire is worn and almost bald. | | |
| Rear Left Inner Tire | The tire is worn and should be replaced. | | |
| Rear Left Outer Tire | The tire is worn and almost bald. | | |
| Rear Axle | The rear axle has an oil mark. The flange gasket may be leaking and the differential oil may need to be changed. | | |
| Fuel Tank | An oil mark is spread around the tank and may indicate a leak. | | |
| Front Right Mud Flap | The mud flap is torn. | | |
| Rear Doors | The left door has small dents and scratches. The right side has minor scratches. | | |
| Rear Door Seals | The seals are torn and damaged. | | |
| Cab Paint | The cab has minor paint damage. | | |
| Decals | The door decals are peeling off. | | |
| Driver's Seat | The seat cover has stain marks and appears to have small holes. | | |
| Floor Mat | The floor mat is slightly torn and damaged. | | |
| Passenger's Seat | The seat cover is stained and has small holes. | | |
| Interior Condition | The door panels, floor and dash are dirty and need to be cleaned. | | |
| Rear Bumper | The rear bumper frame is dented. | | |































































































































































































