

2018 ISUZU NPR-HD / N/A

Specifications

Year	2018
Make	Isuzu
Model	NPR-HD
Date of Inspection	06/15/2023
Location of Inspection	120 Murphy Rd, Hartford, CT, 06114
VIN	JALC4W162J7008356
GVWR	14,500 lbs
Odometer	198,538
Engine Hours	5,364
EMS Warning Lights	No Active Warnings
Cab Interior	Good Condition
Driver's Seat	Good Condition
Passenger's Seat	Good Condition
Transmission Type	Automatic
Pedals	Good Condition
Floorboard	Good Condition
Radio	Yes
A/C	Yes
Switches and Controls	Good Condition
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	Good Condition
Mirrors	Good Condition
Steps	Good Condition
Handrails	Good Condition
Exhaust Pipe	Good Condition
Engine Compartment	See Notes
Oil Dipstick	See Notes
Coolant Level	See Notes
Suspension	Good Condition
Axles	Good Condition
Front Lights	Operational
Rear Lights	Operational
Left Steer Tire Condition	Good Condition
Left Steer Tire Brand	Firestone
Left Steer Tire Size	LT 215/85R16
Rear Left Outer Drive Tire Condition	Good Condition
Rear Left Outer Drive Tire Brand	Firestone
Rear Left Outer Drive Tire Size	LT 215/85R16
Rear Left Inner Drive Tire Condition	Good Condition
Right Steer Tire Condition	Good Condition

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/PCF5GLZDvF49exfSG>

Notes / Description

Due to the unit being parked next to other vehicles, it was not possible to capture all sides and angles of the truck. The cab tilting latch was jammed or not linked to the access lever. Therefore, it was not possible to capture the engine compartment and its items. The inspector was unable to locate the transmission specs sticker. The engine information was confirmed through a VIN-decoding software.



Aspen Field Services

Job #: 56155 / 06-16-2023

VIN: JALC4W162J7008356

Right Steer Tire Brand	Firestone
Right Steer Tire Size	LT 215/85R16
Rear Right Outer Drive Tire Condition	Good Condition
Rear Right Outer Drive Tire Brand	Firestone
Rear Right Outer Drive Tire Size	LT 215/85R16
Rear Right Inner Drive Tire Condition	Good Condition
Axle Information	F: 5,360 lbs / R: 9,880 lbs
Transmission Information	See Notes
Engine Information	5.2L Isuzu In-Line I1B - 4HK1TC / 215 HP

Visible Damages

Latch	The cab lift latch is jammed.
Rear Bumper	The rear bumper paint is peeling.
Top Lip	The top lip on the rear of the box has a dent.
Rear Door Bolts	The rear door bolts are rusty.
Wheels	The front wheels are rusty.
Frame Rails	The frame rails are rusty.
Windshield	The windshield has a rock chip in the glass on the left side.
Service	The dash shows that the fuel filter and the steering oil services are due.
Side Cover	The side cover is rusty by the exhaust.

Aspen Field Services



Front Left / 06-16-2023



Front Right / 06-16-2023

Aspen Field Services



Rear Left / 06-16-2023



Rear Right / 06-16-2023

Aspen Field Services



Front / 06-16-2023



Rear / 06-16-2023

Aspen Field Services



Box Interior / 06-15-2023



VIN: JALC4W162J7008356 / GVWR: 14,500 lbs / Axle Information / 06-15-2023

Aspen Field Services



Odometer: 198,538 / 06-15-2023



Engine Hours: 5,364 / 06-15-2023

Aspen Field Services



EMS Warning Lights / 06-15-2023



Front Lights / 06-15-2023

Aspen Field Services



Front Lights / 06-15-2023



Rear Lights / 06-15-2023

Aspen Field Services



Rear Lights / 06-15-2023



Exhaust Pipe / 06-15-2023

Aspen Field Services



Mirrors / 06-15-2023



Mirrors / 06-15-2023

Aspen Field Services



Steps / 06-15-2023



Steps / 06-15-2023

Aspen Field Services



Steps / 06-15-2023



Handrails / 06-15-2023

Aspen Field Services



Handrails / 06-15-2023



Handrails / 06-15-2023

Aspen Field Services



Handrails / 06-15-2023



Handrails / 06-15-2023

Aspen Field Services



Cab Interior / 06-15-2023



Driver's Seat / 06-15-2023

Aspen Field Services



Passenger's Seat / 06-15-2023



Floorboard / 06-15-2023

Aspen Field Services



Pedals / 06-15-2023



Steering Wheel / 06-15-2023

Aspen Field Services



Transmission / 06-15-2023



Switches and Controls / Radio / A/C / 06-15-2023

Aspen Field Services



Switches and Controls / 06-15-2023



Switches and Controls / 06-15-2023

Aspen Field Services



Switches and Controls / 06-15-2023



Switches and Controls / 06-15-2023

Aspen Field Services



Left Steer Tire Condition / 06-15-2023



Left Steer Tire Condition / 06-15-2023

Aspen Field Services



Left Steer Tire Brand / 06-15-2023



Left Steer Tire Size / 06-15-2023

Aspen Field Services



Right Steer Tire Condition / 06-15-2023



Right Steer Tire Condition / 06-15-2023

Aspen Field Services



Right Steer Tire Brand / 06-15-2023



Right Steer Tire Size / 06-15-2023

Aspen Field Services



Axles / Suspension / 06-15-2023



Axles / Suspension / 06-15-2023

Aspen Field Services



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 06-15-2023



Rear Left Outer Drive Tire Brand / 06-15-2023

Aspen Field Services



Rear Left Outer Drive Tire Size / 06-15-2023



Suspension / 06-15-2023

Aspen Field Services



Axles / 06-15-2023



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 06-15-2023

Aspen Field Services



Rear Right Outer Drive Tire Brand / 06-15-2023



Rear Right Outer Drive Tire Size / 06-15-2023

Aspen Field Services



Suspension / 06-15-2023



Axles / Suspension / 06-15-2023

Aspen Field Services



Axles / Suspension / 06-15-2023