



Aspen Field Services

Job #: 59231 /

VIN: 54DC4W1B5JS806342

CAB AND CHASSIS ONLY - GAS 2018 ISUZU NPR-HD / LA126906

Specifications

| | |
|--------------------------------------|----------------------------------------------|
| Year | 2018 |
| Make | Isuzu |
| Model | NPR-HD |
| Date of Inspection | 08/25/2023 |
| Location of Inspection | 2425 Broadway St NE , Minneapolis, MN, 55413 |
| VIN | 54DC4W1B5JS806342 |
| GVWR | 14,500 lbs |
| Odometer | See Notes |
| Engine Hours | See Notes |
| EMS Warning Lights | See Notes |
| Cab Interior | See Notes |
| Driver's Seat | See Notes |
| Passenger's Seat | No Damages Observed |
| Transmission Type | Automatic |
| Pedals | No Damages Observed |
| Floorboard | No Damages Observed |
| Radio | Yes |
| A/C | Yes |
| Switches and Controls | No Damages Observed |
| Power Mirrors | No |
| Heated Mirrors | Yes |
| Steering Wheel | No Damages Observed |
| Mirrors | No Damages Observed |
| Steps | No Damages Observed |
| Handrails | No Damages Observed |
| Exhaust Pipe | Single - No Damages Observed |
| Engine Compartment | No Damages Observed |
| Oil Dipstick | Good Level / Good Color |
| Coolant Level | Low Level |
| Suspension | Leaf Spring - No Damages Observed |
| Axles | No Damages Observed |
| Front Lights | See Notes |
| Rear Lights | See Notes |
| Left Steer Tire Condition | No Damages Observed |
| Left Steer Tire Brand | Firestone |
| Left Steer Tire Size | 225/70R19.5 |
| Rear Left Outer Drive Tire Condition | No Damages Observed |
| Rear Left Outer Drive Tire Brand | Firestone |
| Rear Left Outer Drive Tire Size | 225/70R19.5 |
| Rear Left Inner Drive Tire Condition | No Damages Observed |

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/wvznjW8McForG22zw>

Notes / Description

The unit had a dead battery and some items could not be verified. The engine information was obtained through a VIN-decoding software.

Mechanic Notes

The rear frame rails have been cut with a torch probably to remove the box from the unit. Aftermarket light bracket has been installed on the rear of the unit.



Aspen Field Services

Job #: 59231 /

VIN: 54DC4W1B5JS806342

| | |
|---------------------------------------|------------------------------------|
| Right Steer Tire Condition | No Damages Observed |
| Right Steer Tire Brand | Firestone |
| Right Steer Tire Size | 225/70R19.5 |
| Rear Right Outer Drive Tire Condition | No Damages Observed |
| Rear Right Outer Drive Tire Brand | Firestone |
| Rear Right Outer Drive Tire Size | 225/70R19.5 |
| Rear Right Inner Drive Tire Condition | No Damages Observed |
| Axle Information | GAWR F: 6,630 lbs / R: 11,020 lbs |
| Transmission Information | Could Not Be Located |
| Engine Information | 6L GM V-Shaped L96 - E85 MAX, IRON |

Visible Damages

| | |
|-------------------|---------------------------------------------------------------------|
| Fuel Tank | The fuel tank is bent and rusty. |
| Coolant | The coolant is low in the reservoir. |
| Kick Panel Screws | The right kick panel screws are missing. |
| Shocks | The front shocks are leaking. |
| Front Wheels | The wheels are rusty and need to be cleaned and painted. |
| Frame Rails | The frame rails are rusty and need to be cleaned and painted. |
| Rear Wheels | The rear outer wheels are rusty and need to be cleaned and painted. |
| Rear Differential | The rear differential is rusty. |
| Driver's Seat | The driver's seat bottom cushion has small stains. |
| Batteries | The unit's batteries are dead. |

Aspen Field Services



Front Left / 08-25-2023



Front Right / 08-25-2023

Aspen Field Services



Rear Left / 08-25-2023



Rear Right / 08-25-2023

Aspen Field Services



Left / 08-25-2023




Front / 08-25-2023

Aspen Field Services



Rear / 08-25-2023



VIN: 54DC4W1B5JS806342 / GVWR: 14,500 lbs / Axle Information / 08-25-2023

Aspen Field Services



Engine Compartment / 08-25-2023



Engine Compartment / 08-25-2023

Aspen Field Services



Coolant Level / 08-25-2023



Oil Dipstick / 08-25-2023

Aspen Field Services



Exhaust Pipe / 08-25-2023



Mirrors / 08-25-2023

Aspen Field Services



Mirrors / 08-25-2023



Steps / 08-25-2023

Aspen Field Services



Handrails / 08-25-2023



Handrails / 08-25-2023

[illegible]

| |
|------------------------|
| Handrails / 08-25-2023 |
|------------------------|



Steps / 08-25-2023

Aspen Field Services



Handrails / 08-25-2023



Handrails / 08-25-2023

Aspen Field Services



Handrails / 08-25-2023



Cab Interior / 08-25-2023

Aspen Field Services



Floorboard / 08-25-2023



Pedals / 08-25-2023

Aspen Field Services



Driver's Seat / 08-25-2023



Steering Wheel / 08-25-2023

Aspen Field Services



Floorboard / 08-25-2023



Passenger's Seat / 08-25-2023

Aspen Field Services



Switches and Controls / 08-25-2023



Switches and Controls / 08-25-2023

Aspen Field Services



Switches and Controls / 08-25-2023



Switches and Controls / Heated Mirrors / Radio / A/C / 08-25-2023

Aspen Field Services



Transmission / 08-25-2023



Right Steer Tire Condition / 08-25-2023

Aspen Field Services



Right Steer Tire Condition / 08-25-2023




Right Steer Tire Brand / 08-25-2023

Aspen Field Services



Right Steer Tire Size / 08-25-2023



Axles / Suspension / 08-25-2023

A close-up photograph of a truck wheel. The wheel features a white-painted metal rim that is heavily rusted, particularly around the central hub and the five lug nut locations. The tire is black and shows signs of wear. On the sidewall of the tire, the brand name 'FIRESTONE' is embossed in large, bold letters. Below it, 'F555' is also embossed. Other markings on the tire include 'RECOOVABLE' and 'MAXIMUM LOAD'. The tire is mounted on a truck, with various mechanical components and a black fender visible in the background. The overall scene is brightly lit, suggesting an outdoor setting during the day.

| |
|----------------------------------------|
| Left Steer Tire Condition / 08-25-2023 |
|----------------------------------------|



| |
|----------------------------------------|
| Left Steer Tire Condition / 08-25-2023 |
|----------------------------------------|

Aspen Field Services



Left Steer Tire Brand / 08-25-2023



Left Steer Tire Size / 08-25-2023

Aspen Field Services



Axles / Suspension / 08-25-2023



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 08-25-2023

Aspen Field Services



Rear Left Outer Drive Tire Brand / 08-25-2023



Rear Left Outer Drive Tire Size / 08-25-2023

Aspen Field Services



Axles / 08-25-2023



Suspension / 08-25-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 08-25-2023



Rear Right Outer Drive Tire Brand / 08-25-2023

Aspen Field Services




Rear Right Outer Drive Tire Size / 08-25-2023



Suspension / 08-25-2023

Aspen Field Services



Axles / 08-25-2023