



Aspen Field Services

Job #: 60621 /

VIN: JALE5W160L7300466

18' MORGAN DRY VAN BODY WITH MAXON TE-25 LIFTGATE, DIESEL 2020 ISUZU NRR / LA130010

Specifications	
Year	2020
Make	Isuzu
Model	NRR
Date of Inspection	09/21/2023
Location of Inspection	3775 Interstate Park Rd W, Riviera Beach, FL, 33404
VIN	JALE5W160L7300466
GVWR	19,500 lbs
Odometer	89,070
Engine Hours	2,958
EMS Warning Lights	No Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	High Level / Dark In Color
Coolant Level	Good Level
Suspension	Leaf Spring - No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	See Notes
Left Steer Tire Brand	Sumitomo
Left Steer Tire Size	225/70R19.5
Rear Left Outer Drive Tire Condition	See Notes
Rear Left Outer Drive Tire Brand	Uniroyal
Rear Left Outer Drive Tire Size	225/70R19.5

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/YsgqiLBuTCX2begqe>

Notes / Description

The engine information was confirmed through VIN decoder.



Aspen Field Services

Job #: 60621 /

VIN: JALE5W160L7300466

Rear Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	See Notes
Right Steer Tire Brand	Sumitomo
Right Steer Tire Size	225/70R19.5
Rear Right Outer Drive Tire Condition	No Damages Observed
Rear Right Outer Drive Tire Brand	Falken
Rear Right Outer Drive Tire Size	225/70R19.5
Rear Right Inner Drive Tire Condition	See Notes
Axle Information	GAWR F: 7,275 lbs / R: 13,660 lbs
Transmission Information	Could Not Be Located
Engine Information	5.2L In-Line Isuzu 4HK1-TC

Visible Damages

Taillight	The left taillight grommet is damaged.
Engine Oil	The oil is dark in color and high on the dipstick.
Rear Right Inner Drive Tire	The tire tread appears to be worn out.
Rear Left Outer Drive Tire	The tire tread appears to be worn out.
Right Steer Tire	The tread is uneven.
Left Steer Tire	The tread is uneven.
Fuel Tank	The side of the tank is dented.

Aspen Field Services



Front Left / 09-21-2023



Front Right / 09-21-2023

Aspen Field Services



Rear Left / Cargo / 09-21-2023



Rear Right / Cargo / 09-21-2023

Aspen Field Services




Front / 09-21-2023



Rear / Cargo / 09-21-2023

Aspen Field Services



VIN: JALE5W160L7300466 / GVWR: 19,500 lbs / Axle Information / 09-21-2023



Odometer: 89,070 / Engine Hours: 2,958 / 09-21-2023

Aspen Field Services



EMS Warning Lights / 09-21-2023



Cab Interior / 09-21-2023

Aspen Field Services



Floorboard / Pedals / 09-21-2023



Driver's Seat / 09-21-2023

Aspen Field Services



Switches and Controls / 09-21-2023



Steering Wheel / 09-21-2023

Aspen Field Services



Switches and Controls / 09-21-2023



Switches and Controls / Heated Mirrors / 09-21-2023

Aspen Field Services



Switches and Controls / Radio / A/C / 09-21-2023



Transmission / 09-21-2023

Aspen Field Services



Floorboard / 09-21-2023



Passenger's Seat / 09-21-2023

A close-up photograph of the side door area of a vehicle. The image shows a black plastic trim piece on the left, a black plastic footrest in the center, and a black plastic door sill plate on the right. The vehicle's body is white. The ground is paved with asphalt.

Steps / 09-21-2023



Handrails / 09-21-2023

Aspen Field Services



Handrails / 09-21-2023



Handrails / 09-21-2023

Aspen Field Services



Mirrors / 09-21-2023



Mirrors / 09-21-2023

Aspen Field Services



Steps / 09-21-2023



Handrails / 09-21-2023

Aspen Field Services



Handrails / 09-21-2023



Handrails / 09-21-2023

Aspen Field Services



Exhaust Pipe / 09-21-2023



Box Interior / 09-21-2023

Aspen Field Services



Rear Lights / 09-21-2023



Rear Lights / 09-21-2023

Aspen Field Services




Front Lights / 09-21-2023



Front Lights / 09-21-2023

Aspen Field Services



Engine Compartment / 09-21-2023



Engine Compartment / 09-21-2023

Aspen Field Services



Coolant Level / 09-21-2023



Oil Dipstick / 09-21-2023

Aspen Field Services



Left Steer Tire Condition / 09-21-2023



Left Steer Tire Condition / 09-21-2023

Aspen Field Services



Left Steer Tire Brand / 09-21-2023



Left Steer Tire Size / 09-21-2023

Aspen Field Services



Axles / Suspension / 09-21-2023



Right Steer Tire Condition / 09-21-2023

Aspen Field Services



Right Steer Tire Condition / 09-21-2023



Right Steer Tire Brand / 09-21-2023

Aspen Field Services



Right Steer Tire Size / 09-21-2023



Axles / Suspension / 09-21-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / 09-21-2023



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 09-21-2023

Aspen Field Services



Rear Right Outer Drive Tire Brand / 09-21-2023



Rear Right Outer Drive Tire Size / 09-21-2023

Aspen Field Services



Axles / Suspension / 09-21-2023



Axles / Suspension / 09-21-2023

Aspen Field Services



Rear Left Outer Drive Tire Condition / 09-21-2023



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 09-21-2023

Aspen Field Services



Rear Left Outer Drive Tire Brand / 09-21-2023



Rear Left Outer Drive Tire Size / 09-21-2023

Aspen Field Services



Axles / Suspension / 09-21-2023



Axles / Suspension / 09-21-2023