



## Aspen Field Services

Job #: 63540 /

VIN: JALC4W160M7006108

# DIESEL 2021 ISUZU NPR-HD CAB AND CHASSIS / LA135314

### Specifications

Year	2021
Make	Isuzu
Model	NPR-HD
Date of Inspection	11/29/2023
Location of Inspection	3775 Interstate Park Road West, Riviera Beach, FL, 33404
VIN	JALC4W160M7006108
GVWR	14,500 lbs
Odometer	167,402
Engine Hours	3,959
EMS Warning Lights	No Active Warnings
Cab Interior	See Notes
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	See Notes
Oil Dipstick	Good Level / Good Color
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Firestone
Left Steer Tire Size	LT215/85R16
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Firestone
Left Outer Drive Tire Size	LT215/85R16
Left Inner Drive Tire Condition	No Damages Observed

### Equipment Photo



### Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/44rZE6R6h2FQXDujE>

### Notes / Description

Part of the unit's engine information was obtained from a VIN-decoding software.



## Aspen Field Services

Job #: 63540 /

VIN: JALC4W160M7006108

Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Firestone
Right Steer Tire Size	LT215/85R16
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	Firestone
Right Outer Drive Tire Size	LT215/85R16
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	Front: 5,360 lbs / Rear: 9,880 lbs
Transmission Information	Could Not Be Located
Engine Information	Isuzu 5.2L In-Line 4HK1-TC

### Visible Damages

Taillights	The taillights and bracket are missing.
Engine And Oil Filter	It appears that a service is due in 461 miles.
Coolant	The coolant is low in the reservoir.
Fuel Tank Leaking	The tank and frame rails are wet. The tank could possibly be leaking.
Plugs	There are plugs hanging down by the gas pedal.
Glove Box Latch	The cover for the glove box is not latched in the photo, the latch is possibly not operational.
Windshield Seal	The seal is warped on the corners of the glass.
Windshield Wipers	The wipers are not operational.
Rubber Fill Neck	The rubber fuel hose going into the rear tank is missing.



# Aspen Field Services



Front Left / 11-29-2023



Front / Front Lights / 11-29-2023



# Aspen Field Services



Front Right / 11-29-2023



Rear Left / 11-29-2023



# Aspen Field Services



Rear / Rear Lights / 11-29-2023



Rear Right / 11-29-2023



# Aspen Field Services



Left / 11-29-2023



Right / 11-29-2023



# Aspen Field Services



VIN: JALC4W160M7006108 / GVWR: 14,500 lbs / Axle Information / 11-29-2023



EMS Warning Lights / 11-29-2023



## Aspen Field Services



Odometer: 167,402 / 11-29-2023



Engine Hours: 3,959 / 11-29-2023



# Aspen Field Services



Cab Interior / 11-29-2023



Floorboard / 11-29-2023



## A close-up photograph of the front left side of a white vehicle. The image shows the lower portion of the front fender, the front wheel, and a black plastic footwell plate. The footwell plate is mounted to the underside of the fender with several screws and features a grid-like pattern for traction. The tire is a black rubber tire with the word "TRANSFORCE" visible on the sidewall. The vehicle is parked on a light-colored gravel surface.

Steps / 11-29-2023



Handrails / 11-29-2023
------------------------



# Aspen Field Services



Handrails / 11-29-2023



Passenger's Seat / 11-29-2023



# Aspen Field Services



Mirrors / 11-29-2023



Handrails / 11-29-2023



# Aspen Field Services



Cab Interior / Handrails / 11-29-2023



Floorboard / 11-29-2023



# Aspen Field Services



Driver's Seat / 11-29-2023



Steps / 11-29-2023



# Aspen Field Services



Pedals / 11-29-2023



Switches and Controls / 11-29-2023



# Aspen Field Services



Steering Wheel / 11-29-2023



Switches and Controls / 11-29-2023



# Aspen Field Services



Switches and Controls / A/C / Radio / Transmission Type / 11-29-2023



Mirrors / 11-29-2023



# Aspen Field Services



Engine Compartment / 11-29-2023



Engine Compartment / 11-29-2023



# Aspen Field Services



Oil Dipstick / 11-29-2023



Coolant Level / 11-29-2023



# Aspen Field Services



Engine Information / 11-29-2023



Left Steer Tire Condition / 11-29-2023



# Aspen Field Services



Left Steer Tire Brand / 11-29-2023



Left Steer Tire Size / 11-29-2023



## Aspen Field Services



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 11-29-2023



Left Outer Drive Tire Condition / 11-29-2023



# Aspen Field Services



Left Outer Drive Tire Brand / 11-29-2023



Left Outer Drive Tire Size / 11-29-2023



# Aspen Field Services



Suspension / Axles / 11-29-2023



Right Outer Drive Tire Condition / 11-29-2023



# Aspen Field Services



Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 11-29-2023



Right Outer Drive Tire Brand / 11-29-2023



# Aspen Field Services



Right Outer Drive Tire Size / 11-29-2023



Suspension / Axles / 11-29-2023



# Aspen Field Services



Exhaust / 11-29-2023



Exhaust / 11-29-2023



# Aspen Field Services



Right Steer Tire Condition / 11-29-2023



Right Steer Tire Condition / 11-29-2023



# Aspen Field Services



Right Steer Tire Brand / 11-29-2023



Right Steer Tire Size / 11-29-2023



# Aspen Field Services



Axles / Suspension / 11-29-2023



Axles / Suspension / 11-29-2023