



# Aspen Field Services

Job #: 65976 /

VIN: 1GCPAAEK5NZ628201

## PICK UP BODY WITH RACK AND TOOL BOX, GAS 2022 C1500 SILVERADO / LA143352

Specifications	
Year	2022
Make	Chevrolet
Model	Silverado
Date of Inspection	01/17/2024
Location of Inspection	2323 W Bell Road, Phoenix, AZ, 85023
VIN	1GCPAAEK5NZ628201
GVWR	6,800 lbs
Odometer	See Notes
Engine Hours	See Notes
EMS Warning Lights	See Notes
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	Yes
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	N/A
Handrails	No Damages Observed
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Good Level / Good Color
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Bed Condition	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Toyo
Left Steer Tire Size	265/70R17
Rear Left Drive Tire Condition	No Damages Observed
Rear Left Drive Tire Brand	Toyo
Rear Left Drive Tire Size	265/70R17
Right Steer Tire Condition	No Damages Observed



**Video Inspection Link**  
<https://app.aspenfieldservices.com/jobs/video/6KQAxhpAkBfA7FasT>

**Notes / Description**  
 The unit's engine information was obtained from a VIN-decoding software. The unit had dead batteries during the inspection. As a result, we could not verify the EMS warning lights, the odometer, and the engine hours.



# Aspen Field Services

Job #: 65976 /

VIN: 1GCPAAEK5NZ628201

Right Steer Tire Brand	Toyo
Right Steer Tire Size	265/70R17
Rear Right Drive Tire Condition	No Damages Observed
Rear Right Drive Tire Brand	Toyo
Rear Right Drive Tire Size	265/70R17
Axle Information	GAWR F: 3,700 lbs / R: 3,800 lbs
Transmission Information	Could Not Be Located
Engine Information	2.7L In-Line L3B L4, SIDI, VVT, ALUM

Visible Damages	
Paint	The front right paint is scratched off.
Body Damage	There is a dent below the rear right door on the body.
Jack	The jack is missing under the seat.
Coolant Level	The coolant is low in the reservoir.
Rack And Tool Box	The rack and tool box are missing from the truck.
Battery	The unit has a dead battery.

# Aspen Field Services



Front Left / 01-18-2024



Front Right / 01-17-2024

# Aspen Field Services



Rear Left / 01-17-2024



Rear Right / 01-18-2024

# Aspen Field Services



Left / 01-17-2024



Right / 01-17-2024

# Aspen Field Services



Front / 01-17-2024




Rear / 01-17-2024

# Aspen Field Services



VIN: 1GCPAAEK5NZ628201 / 01-17-2024



GVWR: 6,800 / Axle Information / 01-17-2024

# Aspen Field Services



Cab Interior / Power Mirrors / 01-17-2024




Floorboard / 01-17-2024

# Aspen Field Services



Pedals / 01-17-2024



Driver's Seat / 01-17-2024

# Aspen Field Services



Steering Wheel / 01-17-2024



Switches and Controls / 01-17-2024

# Aspen Field Services



Switches and Controls / Radio / A/C / Heated Mirrors / 01-17-2024



Transmission / 01-17-2024

# Aspen Field Services



Mirrors / 01-17-2024



Passenger's Seat / 01-17-2024

# Aspen Field Services



Floorboard / 01-17-2024



Handrails / 01-17-2024

# Aspen Field Services



Mirrors / 01-17-2024



Handrails / 01-17-2024

# Aspen Field Services



Cab Interior / Passenger's Seat / 01-17-2024



Floorboard / 01-17-2024

# Aspen Field Services



Handrails / 01-17-2024



Handrails / 01-17-2024

# Aspen Field Services



Floorboard / 01-17-2024



Mirrors / 01-17-2024

# Aspen Field Services



Engine Compartment / 01-17-2024



Coolant Level / 01-17-2024

# Aspen Field Services



Engine Compartment / 01-17-2024



Engine Compartment / 01-17-2024

# Aspen Field Services



Oil Dipstick / 01-17-2024



Exhaust Pipe / 01-17-2024

# Aspen Field Services



Front Lights / 01-18-2024



Rear Lights / 01-17-2024

# Aspen Field Services



Bed Condition / 01-17-2024



Bed Condition / 01-17-2024

# Aspen Field Services



Left Steer Tire Condition / 01-17-2024



Left Steer Tire Brand / 01-17-2024

# Aspen Field Services




Left Steer Tire Size / 01-17-2024



Left Steer Tire Condition / 01-17-2024

# Aspen Field Services



Suspension / 01-17-2024



Suspension / 01-17-2024

# Aspen Field Services



Rear Left Drive Tire Condition / 01-17-2024



Rear Left Drive Tire Brand / 01-17-2024

# Aspen Field Services



Rear Left Drive Tire Size / 01-17-2024



Rear Left Drive Tire Condition / 01-17-2024

# Aspen Field Services



Axles / 01-17-2024



Axles / Suspension / 01-17-2024

# Aspen Field Services



Rear Right Drive Tire Condition / 01-17-2024



Rear Right Drive Tire Brand / 01-17-2024

# Aspen Field Services



Rear Right Drive Tire Size / 01-17-2024



Rear Right Drive Tire Condition / 01-17-2024

# Aspen Field Services



Axles / 01-17-2024



Axles / Suspension / 01-17-2024

# Aspen Field Services



Suspension / 01-17-2024



Right Steer Tire Condition / 01-18-2024

# Aspen Field Services



Right Steer Tire Brand / 01-17-2024



Right Steer Tire Size / 01-17-2024

# Aspen Field Services



Right Steer Tire Condition / 01-17-2024



Suspension / 01-17-2024

# Aspen Field Services



Axles / Suspension / 01-17-2024