











Inspection Detail				
Client:	Isuzu Finance			
Inspected by:	Tracey Judd			
Location of Inspection:	2323 W Bell Rd, Phoenix, AZ 85023, USA			
Phone No / Email:	+1 916 500 3500 / msnider@vtaig.com			
Date of Inspection:	10/14/2024 Job#: 8689z6383		8689z6383	
Year:	2021	Make:	Diesel	
Model:	2500HD Silverado	VIN / SN:	3GCNWAEF3MG379486	



Inspection Details									
Unit Information									
GVWR:		6,800 lbs	Odometer:	80,052	Engine Hours:	2,836	2,836 EMS Warnin Lights:		Yes
				Interio	or Details				
Interior:		No Damages Ob	oserved	Driver's Seat:	No Damages Observed	Passenger's	Passenger's Seat: No Damages Observe		es Observed
Transmission Type	:	Automatic		Pedals:	No Damages Observed	Floorboard	Floorboard: No Damages Observ		ges Observed
Radio:		Yes		A/C:	Yes	Switches an	Switches and Controls: No Damages Observed		es Observed
Power Mirrors:		Yes		Heated Mirrors:	No	Steering Wi	Steering Wheel: See Notes		
Cab Mirror:		No Damages Ob	oserved						
Exterior Details									
Mirrors:		No Damages Ob	oserved	Steps:	No Damages Observed	Handrails:		No Damage	es Observed
Exhaust System:		No Damages Ob	oserved	Front Lights:	No Damages Observed	Rear Lights	:	No Damage	es Observed
Suspension:		No Damages Ob	oserved	Axles:	No Damages Observed				
Engine Details									
Engine Compartme	ent:	See Notes		Oil Dipstick:	Good Level / Good Color	Coolant Lev	vel:	Good Level	
Observations / Comments									



Tires Details					
First Left Steer Tire Condition:	See Notes	First Left Steer Tire Brand:	Kumho	First Left Steer Tire Size:	255/70R17 112T
First Right Steer Tire Condition:	See Notes	First Right Steer Tire Brand:	Kumho	First Right Steer Tire Size:	255/70R17 112T
First Left Outer Drive Tire Condition:	See Notes	First Left Outer Drive Tire Brand:	Kumho	First Left Outer Drive Tire Size:	255/70R17 112T
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	Kumho	First Right Outer Drive Tire Size:	255/70R17 112T



Repair Items					
Item Name	Item Labor Cost	Item Part Cost	Total Cost		
Bed Liner	\$150.00	\$290.00	\$440.00		
Driveline	\$150.00	\$600.00	\$750.00		
Windshield	\$150.00	\$630.00	\$780.00		
Front Lower Bumper	\$150.00	\$430.00	\$580.00		



Wear and Tear Items				
Item Name	Item Comments			
First Left Steer Tire	The tire exhibits wear on the outer shoulder and cracking between the treads.			
First Right Steer Tire	The tire shows signs of wear on the shoulders.			
First Left Outer Drive Tire	The tire has cracks on the sidewall.			
Driveline	The driveline shows signs of scratching and may have a dent in the tube.			
Engine Compartment	The engine compartment is dirty and displays dried mud splatter on various engine components.			
Bed Liner	The top rails of the bed liner exhibit gouges, and the liner within the bed is not securely fitted against the sides.			
Paint	The paint on the lower door jamb on the driver's side shows signs of wear.			
Windshield	The windshield has multiple cracks in the glass.			
Steering Wheel	The material of the steering wheel shows signs of wear.			
Low Tire Pressure Warning	A warning indicating low tire pressure is present on the dashboard.			
Passenger's Door	The door exhibits two minor dents at the bottom.			
Front Lower Bumper	The plastic below the front bumper appears to be goued.			

























































































































































































































































































