

Isuzu Vehicle HEALTH REPORT



**General Information**

Beginning Report Date: Vehicle Production Date  
 Ending Report Date: 2020-12-28 17:02:31  
 VIN: JALC4J167H7003084  
 Current Mileage: 79425 Miles  
 Rear Body Type: Dry Box  
 Freight Type: Agricultural Products  
 Customer Name: Pressure Pro's  
 Customer Email: .  
 Customer Address: .

Country: US

**Fuel Economy Summary**

Distance Traveled: 79,866.01 Miles  
 Fuel Consumed: 7,361.35 Gallons  
 Average Fuel Economy: 10.85 MPG

**Engine/Emission Condition Summary**

Engine Coolant Overtemperature Frequency: 30 s  
 Mimamori ECU does not record overspeed events  
 DPF Regeneration Status: Normal (78% Completed)  
 DPF Particulate Matter Accumulation Status: Normal  
 Recent History Diagnostic Trouble Codes:



**Braking Condition Summary**

Driver Braking Rating: 81  
 Braking Energy Rating per Mile: 87  
 Average Brake Pedal Applications per Mile: 1.07



**Legend**

**DPF Regeneration Status**

A value of 0 - 28% indicates that the vehicle is being driven in a manner that may cause auto engine shutdown to prevent engine or DPF damage.  
 A value of 29 - 64% indicates that the vehicle is being driven in a manner that does not regularly complete the regeneration process.  
 A value of 65 - 100% indicates that the vehicle is being driven in a manner that is acceptable for proper regeneration.

**Driver Braking Rating**

A Driver Braking Rating of 0 - 40 indicates that the driver has been braking very aggressively.  
 A Driver Braking Rating of 41 - 70 indicates that the driver has been braking aggressively.  
 A Driver Braking Rating of 71 - 100 indicates that the driver has been braking normally.

**Braking Energy Rating per Mile**

A Braking Energy Rating per Mile of 0 - 40 indicates that the brake system is absorbing vehicle stopping energy at a very high rate.  
 A Braking Energy Rating per Mile of 41 - 70 indicates that the brake system is absorbing vehicle stopping energy at a high rate.  
 A Braking Energy Rating per Mile of 71 - 100 indicates that the brake system is absorbing vehicle stopping energy at a normal rate.


*Disclaimer: Information contained within this report is for the purpose of obtaining supplemental diagnostic information used for servicing or repairing the vehicle.*

Isuzu Vehicle HEALTH REPORT




### Distance Traveled (Miles)

Total: 79,866.01  
Highway Driving: 46,881.4  
City Driving: 32,965.5  
Low Speed Driving: 149.64



### Fuel Consumption (Gallons)

Total: 7,361.35  
Highway Driving: 4,112.53  
City Driving: 2,671.9  
Low Speed Driving: 16.97  
Idling While Driving: 138.28  
Low Speed Idling: 55.16  
Idling While Parked: 366.51  
PTO Operation: 0




Isuzu Vehicle HEALTH REPORT




### Fuel Economy (MPG)

Average: 10.85  
 Highway Driving: 11.4  
 City Driving: 12.34  
 Low Speed Driving: 8.82  
 Avg. (w/o Idling While Parked): 11.42






### Collection Time

Total: 3,093 hr, 41 min, 27 s  
 Highway Driving: 708 hr, 49 min, 24 s  
 City Driving: 985 hr, 1 min, 51 s  
 Low Speed Driving: 27 hr, 48 min, 30 s  
 Idling While Driving: 281 hr, 11 min, 12 s  
 Low Speed Idling: 154 hr, 31 min, 19 s  
 Idling While Parked: 1,106 hr, 51 min, 39 s  
 Ignition On, Engine Off: 0 s



Isuzu Vehicle HEALTH REPORT



Isuzu Vehicle HEALTH REPORT



**DPF Regeneration Count**

Total Requested: 519

Total Completed: 406

**Engine Usage**

Engine Start Cycles: 5,547

Engine Run Time: 3,093 hr, 41 min, 27 s

Engine Rotation Count: 240,149,951.12

**Vehicle Speed**

Vehicle Life Maximum Speed Recorded: [Customer Consent Required]

Current Distance Traveled Over 75 MPH: [Customer Consent Required]

Current Engine Run Time Over 75 MPH: [Customer Consent Required]

**PTO Activation**

PTO Activation Count: 0

PTO Activation Time: 0 s

NOT POSTED TO FLEET  
 UPDATED: 12/28/20 03:02 pm EST



**Shealy Isuzu Truck Sales**  
 1340 Bluff Rd Columbia, South Carolina 29201  
 Phone: (803) 771-0176

Case Number: 7774243 - Repair Order Number: 110846  
 Purchase Order Number: n/a  
 Service Writer: , - Case Date: 12/21/20 11:50 am EST

**Pressure Pros, Inc**

**Address:** PO BOX 4989  
 WEST COLUMBIA, SC 29171  
**Phone:** (803) 463-9356  
**Fax:**  
**Cust #:** 4714

**Unit #:**  
**Asset:** 2017 Isuzu Nprhd **Miles** 79,425  
**Serial #:** 7H7003084  
**VIN:** JALC4J167H7003084  
**Engine:** 4HK1-TC  
**Engine Hours:**



Operation	Operation	Labor	Parts	Core Charge	Total
1	Isuzu Financial Inspection	\$0.00	\$0.00	\$0.00	\$0.00
2	Replace inop lights <b>Parts:</b> (1.0) LAMP; RR COMB,( 97065809, (12.0) SEAL-A-CRIMP BUTT 12-10, (12.0) SEAL-A-CRIMP BUTT 16-14	\$152.50	\$101.14	\$0.00	\$253.64
3	BPM <b>Parts:</b> (1.0) DISPOSAL FILTER.ETC, (1.0) ELEMENT F/FILTER, (1.0) ELEMENT KIT; FU 97780197, (1.0) OIL FILTER, (11.0) CITGARD 600 engine oil 15W40, (11.0) OIL DISPOSAL, (24.0) WIRE TIE BLK 14-1/2, (6.0) PERMATEX PROFESSIONAL STR	\$218.00	\$137.49	\$0.00	\$355.49
4	Cabin Filter <b>Parts:</b> (1.0) FILTER; BLOWER	\$76.25	\$49.49	\$0.00	\$125.74
5	A/C service	\$305.00	\$0.00	\$0.00	\$305.00
6	wiper blades <b>Parts:</b> (2.0) BLADE; WIPER 20	\$20.00	\$22.36	\$0.00	\$42.36
7	Air filter <b>Parts:</b> (1.0) AIR CLEANER FIL 97780233	\$45.75	\$38.93	\$0.00	\$84.68
8	DEF Service and filter <b>Parts:</b> (1.0) FILTER KIT; PUM, (2.0) 2.5 GAL JUG	\$457.50	\$156.45	\$0.00	\$613.95
9	Coolant Service <b>Parts:</b> (4.0) 6/1 GALLON - A/F Hav Conv Green 50/50	\$152.50	\$40.36	\$0.00	\$192.86
10	Trans service <b>Parts:</b> (1.0) GASKET; OIL PAN 98079400, (1.0) STRAINER ASM; O 98079401, (11.0) SCS & DEXRON VI - ATF	\$152.50	\$155.85	\$0.00	\$308.35
11	Power steering service <b>Parts:</b> (3.0) CHV ATF MD-3(12/1QTLR)	\$152.50	\$13.59	\$0.00	\$166.09
12	Brake fluid service <b>Parts:</b> (2.0) BRAKE FLUID 12 OZ.- DOT4	\$152.50	\$10.84	\$0.00	\$163.34
13	Retorque suspension bolts	\$139.00	\$0.00	\$0.00	\$139.00
14	Replace engine belt <b>Parts:</b> (1.0) BELT; A/C CMPR 98163821, (1.0) BELT; COOLING F 98075519	\$152.50	\$62.03	\$0.00	\$214.53
15	Replace seat belt <b>Parts:</b> (1.0) BELT;CTR SEAT,B, (1.0) BELT;CTR SEAT,T	\$152.50	\$151.79	\$0.00	\$304.29

**Notes:** [12/21/2020 at 11:56 am EST] - Unit was checked in at Shealy Isuzu Truck Sales, arrival time: .

**Parts:** \$940.32  
**Labor:** \$2,329.00

Repair status set to Checked-in.

[12/23/2020 at 09:54 am EST] - Invoice has been sent. Once a PO is received the unit will be ready for pickup. Thank you.

Core:	\$0.00
Haz. Waste:	\$0.00
Shop:	\$65.82
Freight:	\$0.00
Tax:	\$80.49
<b>TOTAL:</b>	<b>\$3,415.63</b>

---

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED BY: \_\_\_\_\_

DATE: \_\_\_/\_\_\_/\_\_\_