



Aspen Field Services

Job #: 58893 /

VIN: JALE5W162J7304435

DIESEL 2018 ISUZU NRR / LA124936

Specifications

Year	2018
Make	Isuzu
Model	NRR
Date of Inspection	08/17/2023
Location of Inspection	1463 US Hwy 22, Mountainside, NJ, 07092
VIN	JALE5W162J7304435 (See Notes)
GVWR	19,500 lbs
Odometer	See Notes
Engine Hours	See Notes
EMS Warning Lights	See Notes
Cab Interior	See Notes
Driver's Seat	See Notes
Passenger's Seat	See Notes
Transmission Type	See Notes
Pedals	See Notes
Floorboard	See Notes
Radio	See Notes
A/C	See Notes
Switches and Controls	See Notes
Power Mirrors	See Notes
Heated Mirrors	See Notes
Steering Wheel	See Notes
Mirrors	See Notes
Steps	See Notes
Handrails	See Notes
Exhaust Pipe	Single / No Damages Observed
Engine Compartment	See Notes
Oil Dipstick	Good Level / Dark Color
Coolant Level	Low Level
Suspension	Leaf Spring / No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Neoterra
Left Steer Tire Size	225/70R19.5
Rear Left Outer Drive Tire Condition	See Notes
Rear Left Outer Drive Tire Brand	Toyo
Rear Left Outer Drive Tire Size	225/70R19.5
Rear Left Inner Drive Tire Condition	See Notes

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/6JXjqrZhw9Wv6w2dd>

Notes / Description

The key was missing, therefore several items could not be captured. As the VIN sticker/tag could not be located, the Chassis Number found printed onto the unit's exterior was added to the document.



Aspen Field Services

Job #: 58893 /

VIN: JALE5W162J7304435

Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Neoterra
Right Steer Tire Size	225/70R19.5
Rear Right Outer Drive Tire Condition	No Damages Observed
Rear Right Outer Drive Tire Brand	Continental
Rear Right Outer Drive Tire Size	225/70R19.5
Rear Right Inner Drive Tire Condition	See Notes
Axle Information	See Notes
Transmission Information	See Notes
Engine Information	5.2L Isuzu In-Line I1B - 4HK1TC
Chassis Number	2J7304435 (See Notes)

Visible Damages	
Front Bumper	The bumper is damaged on the left side.
Frame Rails	The frame rails are rusty.
Rear Left Tires	Both tires' shoulders seem to be worn.
Rear Right Inner Drive Tire	The inside tire's shoulder seems worn.
Valve Cover	The engine valve cover is leaking.
Cooler Tube	The charge air cooler tube is rusty.
Coolant	The coolant is low in the reservoir.
Engine Oil	The engine oil is dark in color.
Mirror	The step mirror is missing from the right door.
Keys	The keys are missing for the unit.

Aspen Field Services



Front / 08-17-2023



Front Right / 08-17-2023

Aspen Field Services



Front Left / 08-17-2023



Exhaust Pipe / 08-17-2023

Aspen Field Services



Mirrors / 08-17-2023



Mirrors / 08-17-2023

Aspen Field Services



Front Lights / 08-17-2023



Rear Lights / 08-17-2023

Aspen Field Services



Chassis Number: 2J7304435 / 08-17-2023



GVWR: 19,500 lbs / 08-17-2023

Aspen Field Services



Right Steer Tire Condition / 08-17-2023



Mirrors / 08-17-2023

Aspen Field Services



Axles / Suspension / 08-17-2023



Right Steer Tire Brand / 08-17-2023

Aspen Field Services



Right Steer Tire Size / 08-17-2023



Left Steer Tire Condition / 08-17-2023

Aspen Field Services



Left Steer Tire Condition / 08-17-2023



Axles / Suspension / 08-17-2023

Aspen Field Services



Left Steer Tire Brand / 08-17-2023



Left Steer Tire Size / 08-17-2023

Aspen Field Services



Rear Left Outer Drive Tire Condition / 08-17-2023



Rear Left Outer Drive Tire Condition / 08-17-2023

Aspen Field Services



Rear Left Outer Drive Tire Brand / 08-17-2023



Rear Left Outer Drive Tire Size / 08-17-2023

Aspen Field Services



Axles / Suspension / 08-17-2023



Rear Right Outer Drive Tire Condition / 08-17-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / 08-17-2023



Rear Right Outer Drive Tire Brand / 08-17-2023

Aspen Field Services



Rear Right Outer Drive Tire Size / 08-17-2023



Axles / Suspension / 08-17-2023

Aspen Field Services



Engine Compartment / 08-17-2023



Engine Compartment / 08-17-2023

Aspen Field Services



Coolant Level / 08-17-2023



Oil Dipstick / 08-17-2023