



## Aspen Field Services

Job #: 59495 /

VIN: JALE5W16XK7306094

# DIESEL 2019 ISUZU NRR - LA128900 / LA128900

### Specifications

Year	2019
Make	Isuzu
Model	NRR
Date of Inspection	08/30/2023
Location of Inspection	1530 S. 500 West, Salt Lake City, UT, 84115
VIN	JALE5W16XK7306094
GVWR	19,500 lbs
Odometer	151,193
Engine Hours	6,539
EMS Warning Lights	No Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	See Notes
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	Yes
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	Single - No Damages Observed
Engine Compartment	No Damages Observed
Oil Dipstick	Good Level / Dark Color
Coolant Level	Low Level
Suspension	Leaf Spring - No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	No Damages Observed
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Kelly
Left Steer Tire Size	225/70R19.5
Rear Left Outer Drive Tire Condition	No Damages Observed
Rear Left Outer Drive Tire Brand	Goodyear
Rear Left Outer Drive Tire Size	225/70R19.5
Rear Left Inner Drive Tire Condition	No Damages Observed

### Equipment Photo



### Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/JNfAdZ5PHgyAP9ixz>

### Notes / Description

The Engine Information was obtained from a VIN-Decoding software.



## Aspen Field Services

Job #: 59495 /

VIN: JALE5W16XK7306094

Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Kelly
Right Steer Tire Size	225/70R19.5
Rear Right Outer Drive Tire Condition	No Damages Observed
Rear Right Outer Drive Tire Brand	Goodyear
Rear Right Outer Drive Tire Size	225/70R19.5
Rear Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 7,275 lbs / R: 13,660 lbs
Transmission Information	Could Not Be Located
Engine Information	5.2L Isuzu In-Line I1B - 4HK1TC

### Visible Damages

Instrument Cluster	The plastic face has a crack in it
Floor Mat	The floor mat is worn and torn on the driver's side.
Passenger's Seat	The seat has a small hole in the bottom cushion.
Valve Cover	The engine valve cover is leaking.
Coolant	The coolant is low in the reservoir.
Engine Oil	The engine oil is dark in color.

# Aspen Field Services



Front Left / 08-30-2023



Front Right / 08-30-2023



# Aspen Field Services



Rear Left / 08-30-2023



Rear Right / 08-30-2023



# Aspen Field Services



Left / 08-30-2023




Front / 08-30-2023



# Aspen Field Services



Rear / 08-30-2023



VIN: JALE5W16XK7306094 / GVWR: 19,500 lbs / Axle Information / 08-30-2023



# Aspen Field Services



Odometer: 151,193 / Engine Hours: 6,539 / EMS Warning Lights / 08-30-2023



Cab Interior / 08-30-2023



# Aspen Field Services



Floorboard / 08-30-2023



Pedals / 08-30-2023



# Aspen Field Services



Driver's Seat / 08-30-2023



Steering Wheel / 08-30-2023



# Aspen Field Services



Switches and Controls / 08-30-2023



Switches and Controls / 08-30-2023



# Aspen Field Services



Switches and Controls / Heated Mirrors / Radio / A/C / 08-30-2023



Transmission / 08-30-2023



# Aspen Field Services



Floorboard / 08-30-2023



Passenger's Seat / 08-30-2023



# Aspen Field Services



Steps / 08-30-2023



Handrails / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Mirrors / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Handrails / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Mirrors / 08-30-2023



# Aspen Field Services



Handrails / 08-30-2023



Exhaust Pipe / 08-30-2023



# Aspen Field Services



Front Lights / 08-30-2023



Rear Lights / 08-30-2023



# Aspen Field Services



Engine Compartment / 08-30-2023



Engine Compartment / 08-30-2023



## Aspen Field Services



Coolant Level / 08-30-2023



Oil Dipstick / 08-30-2023



# Aspen Field Services



Left Steer Tire Condition / 08-30-2023



Left Steer Tire Condition / 08-30-2023



# Aspen Field Services



Left Steer Tire Brand / 08-30-2023



Left Steer Tire Size / 08-30-2023



## Aspen Field Services



Axles / Suspension / 08-30-2023



Rear Left Outer Drive Tire Condition / 08-30-2023



# Aspen Field Services



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 08-30-2023



Rear Left Outer Drive Tire Brand / 08-30-2023



# Aspen Field Services



Rear Left Outer Drive Tire Size / 08-30-2023



Axles / Suspension / 08-30-2023



# Aspen Field Services



Rear Right Outer Drive Tire Condition / 08-30-2023



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 08-30-2023



# Aspen Field Services



Rear Right Outer Drive Tire Size / 08-30-2023



Rear Right Outer Drive Tire Brand / 08-30-2023



## Aspen Field Services



Axles / Suspension / 08-30-2023



Axles / Suspension / 08-30-2023



# Aspen Field Services



Right Steer Tire Condition / 08-30-2023



Right Steer Tire Condition / 08-30-2023



# Aspen Field Services



Right Steer Tire Brand / 08-30-2023



Right Steer Tire Size / 08-30-2023



## Aspen Field Services



Axles / Suspension / 08-30-2023