



## Aspen Field Services

Job #: 59775 /

VIN: 54DC4W1BXJS804800

# 16' SUPREME DRY VAN, GAS 2018 - ISUZU NPR-HD - LA126721 / LA126721

Specifications	
Year	2018
Make	Isuzu
Model	NPR
Date of Inspection	09/08/2023
Location of Inspection	1401 Harding Ct, Indianapolis, IN, 46217, USA
VIN	54DC4W1BXJS804800
GVWR	14,500 lbs
Odometer	113,323
Engine Hours	N/A
EMS Warning Lights	No Damages Observed
Cab Interior	No Damages Observed
Driver's Seat	See Notes
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Engine Serial Plate	Obstructed
Oil Dipstick	Dark Color / Low Level
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Ironman
Left Steer Tire Size	225/70R19.5
Left Outer Drive Tire Condition	See Notes
Left Outer Drive Tire Brand	Continental
Left Outer Drive Tire Size	225/70R19.5

## Equipment Photo



## Notes / Description

The truck was confirmed to be fully operational. The rear of the frame rails has been cut to remove the box from the truck, and temporary mud flaps are zip-tied to the frame.



## Aspen Field Services

Job #: 59775 /

VIN: 54DC4W1BXJS804800

Left Inner Drive Tire Condition	No Damages Observed
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Ironman
Right Steer Tire Size	225/70R19.5
Right Outer Drive Tire Condition	No Damages Observed
Right Outer Drive Tire Brand	Continental
Right Outer Drive Tire Size	225/70R19.5
Right Inner Drive Tire Condition	No Damages Observed
Axle Information	F: 6,630 LB / R: 11,020 LB
Transmission Information	Obstructed
Engine Information	Obstructed

Visible Damages	
Driver's Seat	The seat has some staining.
Left Outer Drive Tire	The tire tread looks to be worn.
Coolant	The coolant is low in the reservoir.
Engine Oil	The oil is dark in color and low level.
Frame Rails	The frame rails are rusty and need to be cleaned and repainted.
Rear Lights	The rear tail lights are not operational.



# Aspen Field Services



Front Left / 09-11-2023



Front / 09-08-2023



# Aspen Field Services



Front Right / 09-11-2023



Right / 09-08-2023



# Aspen Field Services



Rear Right / 09-11-2023



Rear / 09-11-2023



# Aspen Field Services



Rear Left / 09-11-2023



Left / 09-08-2023



# Aspen Field Services



VIN: 54DC4W1BXJS804800 / GVWR:14,500 lbs / Axle Information / 09-08-2023



Odometer: 113,323 / 09-08-2023



# Aspen Field Services



EMS Warning Lights / 09-08-2023



Passenger's Seat / 09-08-2023



# Aspen Field Services



Transmission / 09-08-2023



Pedals / Floorboard / 09-08-2023



# Aspen Field Services



Floorboard / 09-08-2023



Floorboard / 09-08-2023



# Aspen Field Services



Radio / A/C / Switches and Controls / 09-08-2023



Switches and Controls / 09-11-2023



# Aspen Field Services



Switches and Controls / 09-08-2023



Steering Wheel / 09-08-2023



# Aspen Field Services



Mirrors / 09-08-2023



Mirrors / 09-08-2023



# Aspen Field Services



Driver's Seat / 09-08-2023



Cab Interior / 09-08-2023



# Aspen Field Services



Steps / 09-08-2023



Handrails / 09-08-2023



Handrails / 09-08-2023
------------------------



Handrails / 09-08-2023



# Aspen Field Services



Handrails / 09-08-2023



Steps / 09-08-2023



# Aspen Field Services



Handrails / 09-08-2023



Handrails / 09-08-2023



## Aspen Field Services



Exhaust Pipe / 09-08-2023



Front Lights / 09-08-2023



# Aspen Field Services



Rear Lights / 09-08-2023



Left Steer Tire Condition / 09-08-2023



# Aspen Field Services



Left Steer Tire Brand / 09-08-2023



Left Steer Tire Size / 09-11-2023



## Aspen Field Services



Left Steer Tire Condition / 09-11-2023



Suspension / Axles / 09-08-2023



# Aspen Field Services



Right Steer Tire Condition / 09-08-2023



Right Steer Tire Brand / 09-08-2023



# Aspen Field Services



Right Steer Tire Size / 09-11-2023



Right Steer Tire Condition / 09-08-2023



# Aspen Field Services



Suspension / Axles / 09-08-2023



Right Outer Drive Tire Condition / 09-08-2023



# Aspen Field Services



Right Outer Drive Tire Brand / 09-11-2023



Right Outer Drive Tire Size / 09-11-2023



## Aspen Field Services



Right Inner Drive Tire Condition / Right Outer Drive Tire Condition / 09-08-2023



Suspension / Axles / 09-08-2023



# Aspen Field Services



Left Outer Drive Tire Brand / 09-11-2023



Left Outer Drive Tire Size / 09-11-2023



# Aspen Field Services



Left Steer Tire Condition / 09-08-2023



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 09-11-2023



# Aspen Field Services



Suspension / Axles / 09-08-2023



Engine Compartment / 09-08-2023



# Aspen Field Services



Coolant Level / 09-08-2023



Engine Compartment / 09-08-2023



# Aspen Field Services



Engine Compartment / 09-08-2023



Engine Compartment / 09-08-2023



# Aspen Field Services



Engine Compartment / 09-08-2023



Oil Dipstick / 09-08-2023