



Aspen Field Services

Job #: 63083 /

VIN: JALC4W166L7009318

DIESEL 2020 ISUZU NPR-HD / LA131384 Cab and Chassis

Specifications

Year	2020
Make	Isuzu
Model	NPR
Date of Inspection	12/15/2023
Location of Inspection	4950 Keller Springs Rd Stee 190, Addison, TX, 75001
VIN	JALC4W166L7009318
GVWR	14,500 lbs
Odometer	136,107
Engine Hours	3,203
EMS Warning Lights	No Active Warnings
Cab Interior	No Damages Observed
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission	Automatic
Pedals	No Damages Observed
Floorboard	See Notes
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	Yes
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	See Notes
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Engine Serial Plate	Obstructed
Oil Dipstick	Good Level / Dark Color
Coolant Level	Good Level
Suspension	No Damages Observed
Axles	No Damages Observed
Brakes	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	See Notes
Left Steer Tire Brand	Firestone
Left Steer Tire Size	LT215/85R16
Rear Left Outer Drive Tire Condition	See Notes
Rear Left Outer Drive Tire Brand	Firestone

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/37SZczTP2c4ao6Xpp>


Notes / Description

The engine information was confirmed through VIN decoder. The equipment starts and runs.

Aspen Field Services



Right / 12-15-2023



VIN: JALC4W166L7009318 / GVWR: 14,500 lbs / Axle Information / 12-15-2023

Aspen Field Services



Odometer: 136,107 / 12-15-2023



Engine Hours: 3,203 / 12-15-2023

Aspen Field Services



EMS Warning Lights / 12-15-2023



Cab Interior / 12-15-2023

Aspen Field Services



Driver's Seat / 12-15-2023



Steering Wheel / 12-15-2023

Aspen Field Services



Switches and Controls / 12-15-2023



Switches and Controls / Radio / A/C / 12-15-2023

Aspen Field Services



Switches and Controls / 12-15-2023



Power Mirrors / 12-15-2023

Aspen Field Services



Transmission / 12-18-2023



Floorboard / 12-15-2023

Aspen Field Services



Pedals / 12-15-2023



Handrails / 12-15-2023

Aspen Field Services



Handrails / 12-15-2023



Handrails / 12-15-2023

Aspen Field Services



Steps / 12-15-2023



Mirrors / 12-15-2023

Aspen Field Services



Passenger's Seat / 12-15-2023



Floorboard / 12-15-2023

Aspen Field Services



Handrails / 12-15-2023



Handrails / 12-15-2023

Aspen Field Services



Handrails / 12-15-2023



Steps / 12-15-2023

Aspen Field Services



Mirrors / 12-15-2023



Engine Compartment / 12-15-2023

Aspen Field Services



Engine Compartment / 12-15-2023



Engine Information / 12-15-2023

Aspen Field Services



Oil Dipstick / 12-15-2023



Coolant Level / 12-15-2023

Aspen Field Services



Rear Right Outer Drive Tire Condition / 12-15-2023



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 12-15-2023

Aspen Field Services



Right Steer Tire Condition / 12-15-2023



Right Steer Tire Condition / 12-15-2023