

## 24' MORGAN DRY VAN BODY, DIESEL 2019 ISUZU NRR / LA131070

### Specifications

Year	2019
Make	Izusu
Model	NRR
Date of Inspection	01/02/2024
Location of Inspection	1530 S 500 West , Salt Lake City, UT, 84115
VIN	JALE5W162K7306221
GVWR	19,500 lbs
Odometer	114,899
Engine Hours	6,236
EMS Warning Lights	No Active Warnings
Cab Interior	See Notes
Driver's Seat	See Notes
Passenger's Seat	No Damages Observed
Transmission	No Damages Observed
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	See Notes
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	See Notes
Exhaust Pipe	No Damages Observed
Engine Compartment	No Damages Observed
Engine Serial Plate	8983511090
Oil Dipstick	Good Level / Good Color
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Ironman
Left Steer Tire Size	225/70R19.5
Rear Left Outer Drive Tire Condition	See Notes
Rear Left Outer Drive Tire Brand	Kelly
Rear Left Outer Drive Tire Size	225/70R19.5
Rear Left Inner Drive Tire	No Damages Observed

### Equipment Photo



### Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/Ds6unHraKXBuMq8RD>

### Notes / Description

The Engine Information was verified through VIN Decoder. The equipment starts and runs.



## Aspen Field Services

Job #: 64941 /

VIN: JALE5W162K7306221

Condition	
Right Steer Tire Condition	No Damages Observed
Right Steer Tire Brand	Ironman
Right Steer Tire Size	225/70R19.5
Rear Right Outer Drive Tire Condition	See Notes
Rear Right Outer Drive Tire Brand	Kelly
Rear Right Outer Drive Tire Size	225/70R19.5
Rear Right Inner Drive Tire Condition	No Damages Observed
Axle Information	GAWR F: 7,275 lbs / R: 13,660 lbs
Transmission Information	Could Not Be Located
Engine Information	5.2L In-Line I1B - 4HK1TC
Box of the Truck	See Notes

Visible Damages	
Sheet Metal Panels	The panels on the box are damaged.
Grille	The grille is broken on the right side.
Grab Handles	The grab handles on the rear of the box are bent.
Instrument Cluster	The face on the cluster is cracked.
Driver's Seat	The bottom seat cushion is stained.
Fuse Panel Cover	The cover has been removed and is laying on the seat.
Interior Light	The light is not operational.
Windshield	The glass has rock chips.
Coolant	The coolant is low in the reservoir.
Rear Left Outer Tire	The tire treads are worn out.
Rear Right Outer Tire	The tire treads appear to be worn down.
Rear Bumper	The square tubing is broken off on the rear supports and the supports are bent.
Rear Taillights	The left taillight is not operational and the right one is not fully working.
Rear Door Frame	The right rear frame is dented.
Battery Box Cover	The cover appears to be held in place with a chain possibly the cover is damaged.

# Aspen Field Services



Front Left / 01-02-2024



Front Right / 01-02-2024



# Aspen Field Services



Rear Left / 01-02-2024



Rear Right / 01-02-2024



# Aspen Field Services



Front / Front Lights / 01-02-2024




Rear / Rear Lights / 01-02-2024

# Aspen Field Services



Left / 01-02-2024



VIN: JALE5W162K7306221 / GVWR: 19,500 lbs / Axle Information / 01-02-2024



# Aspen Field Services



Odometer: 114,899 / Engine Hours: 6,236 / EMS Warning Lights / 01-02-2024



Cab Interior / 01-02-2024



# Aspen Field Services



Driver's Seat / 01-02-2024



Steering Wheel / 01-02-2024

# Aspen Field Services



Switches and Controls / 01-02-2024



Switches and Controls / 01-02-2024



# Aspen Field Services



Switches and Controls / 01-02-2024



Switches and Controls / 01-02-2024



# Aspen Field Services



Switches and Controls / 01-02-2024



Transmission / 01-02-2024

# Aspen Field Services



Pedals / 01-02-2024



Floorboard / 01-02-2024



# Aspen Field Services



Handrails / 01-02-2024



Handrails / 01-02-2024



# Aspen Field Services



Handrails / 01-03-2024



Steps / 01-02-2024

# Aspen Field Services



Mirrors / 01-02-2024



Mirrors / 01-02-2024



# Aspen Field Services



Passenger's Seat / 01-02-2024



Floorboard / 01-02-2024



# Aspen Field Services



Switches and Controls / 01-02-2024



Handrails / 01-02-2024

# Aspen Field Services



Handrails / 01-02-2024




Handrails / 01-02-2024



# Aspen Field Services



Steps / 01-02-2024



Engine Compartment / 01-02-2024



# Aspen Field Services



Engine Compartment / 01-02-2024



Engine Serial Plate: 8983511090 / 01-02-2024



## Aspen Field Services



Oil Dipstick / 01-02-2024



Coolant Level / 01-02-2024



# Aspen Field Services



Exhaust Pipe / 01-02-2024



Left Steer Tire Condition / 01-02-2024



# Aspen Field Services



Left Steer Tire Condition / 01-02-2024



Left Steer Tire Brand / 01-02-2024



# Aspen Field Services



Left Steer Tire Size / 01-02-2024



Axles / Suspension / 01-02-2024



## Aspen Field Services



Rear Left Outer Drive Tire Condition / Rear Left Outer Drive Tire Brand / 01-02-2024



Rear Left Outer Drive Tire Condition / Rear Left Inner Drive Tire Condition / 01-02-2024

## Aspen Field Services



Rear Left Outer Drive Tire Size / 01-03-2024



Axles / Suspension / 01-02-2024



## Aspen Field Services



Right Steer Tire Condition / 01-02-2024



Right Steer Tire Condition / 01-02-2024



# Aspen Field Services



Right Steer Tire Brand / 01-02-2024



Right Steer Tire Size / 01-02-2024



# Aspen Field Services



Axles / Suspension / 01-02-2024



First Right Outer Drive Tire Condition / Rear Right Outer Drive Tire Brand / 01-02-2024



# Aspen Field Services



Rear Right Outer Drive Tire Condition / Rear Right Inner Drive Tire Condition / 01-02-2024



Rear Right Outer Drive Tire Size / 01-03-2024



# Aspen Field Services



Axles / Suspension / 01-02-2024



Box Interior / 01-02-2024

# Aspen Field Services



Box Interior / 01-02-2024



Box Interior / 01-02-2024



# Aspen Field Services



Box Interior / 01-02-2024