




Inspection Detail			
	<b>Client:</b>		Isuzu Finance
	<b>Inspected by:</b>		Kristin Stauffer
	<b>Location of Inspection:</b>		2201 W Bell Rd, Phoenix, AZ 85023, USA
	<b>Phone No / Email:</b>		+1 916 500 3500 / msnider@vtaig.com
	<b>Date of Inspection:</b>	<b>Job#:</b>	868cfvevx
	<b>Year:</b>	<b>Make:</b>	Chevrolet
	<b>Model:</b>	<b>VIN / SN:</b>	3GCNWAEF4MG402824

## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Inspection Details****Unit Information**

<b>GVWR:</b>	6,800 lbs	<b>Odometer:</b>	69,252	<b>Engine Hours:</b>	2,706	<b>EMS Warning Lights:</b>	No
--------------	-----------	------------------	--------	----------------------	-------	----------------------------	----

**Interior Details**

<b>Interior:</b>	No Damages Observed	<b>Driver's Seat:</b>	See Notes	<b>Passenger's Seat:</b>	No Damages Observed
<b>Transmission Type:</b>	Automatic	<b>Pedals:</b>	No Damages Observed	<b>Floorboard:</b>	No Damages Observed
<b>Radio:</b>	Yes	<b>A/C:</b>	Yes	<b>Switches and Controls:</b>	No Damages Observed
<b>Power Mirrors:</b>	Yes	<b>Heated Mirrors:</b>	Yes	<b>Steering Wheel:</b>	See Notes
<b>Cab Mirror:</b>	No Damages Observed				

**Exterior Details**

<b>Mirrors:</b>	No Damages Observed	<b>Steps:</b>	No Damages Observed	<b>Handrails:</b>	No Damages Observed
<b>Exhaust System:</b>	No Damages Observed	<b>Front Lights:</b>	No Damages Observed	<b>Rear Lights:</b>	No Damages Observed
<b>Suspension:</b>	No Damages Observed	<b>Axles:</b>	No Damages Observed		

**Engine Details**

<b>Engine Compartment:</b>	No Damages Observed	<b>Oil Dipstick:</b>	Good Level / Good Color	<b>Coolant Level:</b>	Low Level
----------------------------	---------------------	----------------------	-------------------------	-----------------------	-----------

**Observations / Comments**

The unit runs and drives.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



Tires Details					
<b>First Left Steer Tire Condition:</b>	No Damages Observed	<b>First Left Steer Tire Brand:</b>	Michelin	<b>First Left Steer Tire Size:</b>	265/70R17
<b>First Right Steer Tire Condition:</b>	No Damages Observed	<b>First Right Steer Tire Brand:</b>	Michelin	<b>First Right Steer Tire Size:</b>	265/70R17
<b>First Left Drive Tire Condition:</b>	No Damages Observed	<b>First Left Drive Tire Brand:</b>	Michelin	<b>First Left Drive Tire Size:</b>	265/70R17
<b>First Right Drive Tire Condition:</b>	See Notes	<b>First Right Drive Tire Brand:</b>	Michelin	<b>First Right Drive Tire Size:</b>	265/70R17

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Wear and Tear Items	
Item Name	Item Comments
Low Fuel	The fuel gauge is showing the unit is low on fuel.
Coolant	The coolant appears to be low in the reservoir.
Seat Material Stained	The driver's seat material is dirty and stained.
Steering Wheel	The steering wheel has carving in it at the bottom.
Low Tire Pressure Warning	The dash is showing there is a low pressure on the rear right tire.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Left****Front Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Rear Left****Rear Right / Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front****Rear / Rear Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**VIN: 3GCNWAEF4MG402824 / GVWR: 6,800 lbs**



### Unit Condition



### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**EMS Warning Lights**

**EMS Warning Lights**

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Engine Hours: 2,706****Odometer: 69,252****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Steering Wheel****Switches and Controls / Radio****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Switches and Controls / Heated Mirrors / A/C****Switches and Controls****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls / Power Mirrors****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Interior****Pedals****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Pedals / Floorboard****Driver's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Passenger's Seat****Cab Mirror****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.




**Unit Condition****Mirrors / Handrails****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.


**Mirrors / Handrails****Front Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Front Lights****Oil Dipstick****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.


**Oil Dipstick****Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Engine Compartment****Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Engine Compartment****Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles****Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**Axles****Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Steer Tire Condition****First Left Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Steer Tire Size****First Right Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Steer Tire Brand****First Right Steer Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Drive Tire Condition****First Right Drive Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Right Drive Tire Size****First Left Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



**First Left Drive Tire Brand****First Left Drive Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.