



Inspection Detail				
<p style="text-align: center;"><a href="#">Click to watch the video</a></p> 	<b>Client:</b>	Isuzu Finance		
	<b>Inspected by:</b>	Fraylin Mena		
	<b>Location of Inspection:</b>	2201 W Bell Rd, Phoenix, AZ 85023, USA		
	<b>Phone No / Email:</b>	+1 602 881 9525 / tfraser@vtaig.com		
	<b>Date of Inspection:</b>	9/2/2025	<b>Job#:</b>	868fcqcat
	<b>Year:</b>	2022	<b>Make:</b>	Chevrolet
<b>Model:</b>	Express 2500 Cargo	<b>VIN / SN:</b>	1GCWGAFFIN1207353	

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## Inspection Details

### Unit Information

<b>GVWR:</b>	8,600 lbs	<b>Odometer:</b>	26,149	<b>Engine Hours:</b>	See Notes	<b>EMS Warning Lights:</b>	Yes
--------------	-----------	------------------	--------	----------------------	-----------	----------------------------	-----

### Interior Details

<b>Interior:</b>	No Damages Observed	<b>Driver's Seat:</b>	No Damages Observed	<b>Passenger's Seat:</b>	See Notes
<b>Transmission Type:</b>	Automatic	<b>Pedals:</b>	No Damages Observed	<b>Floorboard:</b>	N/A
<b>Radio:</b>	Yes	<b>A/C:</b>	Yes	<b>Switches and Controls:</b>	No Damages Observed
<b>Power Mirrors:</b>	Yes	<b>Heated Mirrors:</b>	No	<b>Steering Wheel:</b>	No Damages Observed
<b>Cab Mirror:</b>	No Damages Observed				

### Exterior Details

<b>Mirrors:</b>	No Damages Observed	<b>Steps:</b>	No Damages Observed	<b>Handrails:</b>	No Damages Observed
<b>Exhaust System:</b>	No Damages Observed	<b>Front Lights:</b>	No Damages Observed	<b>Rear Lights:</b>	See Notes
<b>Suspension:</b>	No Damages Observed	<b>Axles:</b>	No Damages Observed		

### Engine Details

<b>Engine Compartment:</b>	No Damages Observed	<b>Oil Dipstick:</b>	Good Level / Good Color	<b>Coolant Level:</b>	Good Level
----------------------------	---------------------	----------------------	-------------------------	-----------------------	------------

### Observations / Comments

The unit runs and drives, but it required a jump start, the side rear door could not be opened, and the driver reported that the hours were reset.

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tires Details					
<b>Left Steer Tire Condition:</b>	See Notes	<b>Left Steer Tire Brand:</b>	Bridgestone	<b>Left Steer Tire Size:</b>	LT245/75R16
<b>Right Steer Tire Condition:</b>	See Notes	<b>Right Steer Tire Brand:</b>	Bridgestone	<b>Right Steer Tire Size:</b>	LT245/75R16
<b>First Left Outer Drive Tire Condition:</b>	No Damages Observed	<b>First Left Outer Drive Tire Brand:</b>	Cooper	<b>First Left Outer Drive Tire Size:</b>	LT245/75R16
<b>First Right Outer Drive Tire Condition:</b>	No Damages Observed	<b>First Right Outer Drive Tire Brand:</b>	Cooper	<b>First Right Outer Drive Tire Size:</b>	LT245/75R16

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

<b>Repair Items</b>			
<b>Item Name</b>	<b>Item Labor Cost</b>	<b>Item Part Cost</b>	<b>Total Cost</b>
Side Door	\$450.00	\$1,100.00	\$1,550.00
<b>Total Repairs:</b>			<b>\$1,550.00</b>

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

<b>Wear and Tear Items</b>	
<b>Item Name</b>	<b>Item Comments</b>
Battery	The unit's battery had to be jump-started and may need replacement.
Side Door	The unit's rear side door does not open and will need diagnosis and repairs.
Right Steer Tire	The front right steer tire appears to have a nail in the outer edge of the tread and will need to be replaced or repaired.
Tire Rotation	The front tires are more worn than the rear tires and need to be rotated to extend their longevity.
Left Rear Wheel Well	The left rear wheel well on the inside of the unit has a small dent and can be repaired.
Passenger Seat Stained	The passenger's seat appears stained, and debris is on the seat.
Fuel Below 50%	The unit has less than a half tank of fuel and may need to be topped off.
Tire Pressure Light	The front right tire has low pressure, and the left rear tire has low air pressure.
Third Brake Light	The third brake light has the right bulb out, and it can be replaced.
Right Tail Light	The right tail light bulb is out and will need to be replaced.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front Left



Front Right



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Rear Left



Rear Right



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front



Rear



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

VIN: 1GCVGAFP1N1207353



GVWR: 8,600 lbs



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Odometer: 26,149



EMS Panel



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

EMS Panel



EMS Panel




**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Radio / A/C



Switches and Controls / Transmission



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Steering Wheel



Switches and Controls



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Pedals



Switches and Controls



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls



Interior Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Interior Condition / Handrails / Cab Mirror



Passenger's Seat



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Passenger's Seat



Driver's Seat



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Interior Condition



Interior Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Handrails / Cab Mirror



Handrails



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Mirrors



Mirrors



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Steps



Steps



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front Lights



Front Lights



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Rear Lights



Rear Lights



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Oil Dipstick



Oil Dipstick



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Coolant Level



Coolant Level



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment



Engine Compartment



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment



Coolant Level



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment



Engine Compartment




**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment



Engine Compartment



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Undercarriage



Undercarriage



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Exhaust System



Exhaust System



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Suspension / Axles



Suspension / Axles



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Exhaust System



Suspension / Axles



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Suspension / Axles



Interior Condition

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Interior Condition



Interior Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Unit Condition



First Left Steer Tire Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Steer Tire Condition



First Left Steer Tire Brand



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Steer Tire Size



First Left Outer Drive Tire Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Outer Drive Tire Condition



First Left Outer Drive Tire Brand



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Outer Drive Tire Size



First Right Outer Drive Tire Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Outer Drive Tire Condition




First Right Outer Drive Tire Brand



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Outer Drive Tire Size



First Right Steer Tire Condition



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Steer Tire Condition



First Right Steer Tire Brand



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Steer Tire Size



**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.