











Inspection Detail						
Client:	Isuzu Finance					
Inspected by:	Mark Hamilton					
Location of Inspection:	6225 State Rd., Philadelphia, PA 19135, USA					
Phone No / Email:	+1 610 220 0514 / fhalper@bentleytruckservices.com					
Date of Inspection:	4/25/2025 Job#: 868dmgmjm					
Year:	2018 Make: ISUZU					
Model:	FTR VIN: 54DK6S168JSG00601					



Inspection Details

Unit Information					
GVWR:	25,950	Odometer:	145,802	Engine Hours:	6,198
EMS Warning Lights:	Yes				

Interior Details					
Cab Interior:	No Damages Observed	Driver's Seat:	No Damages Observed	Passenger's Seat:	No Damages Observed
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed
Power Mirrors:	Yes	Heated Mirrors:	No	Steering Wheel:	No Damages Observed
Cab Mirror:	N/A	Box Condition:	See Notes		

Exterior Details					
Mirrors:	No Damages Observed	Steps:	See Notes	Handrails:	No Damages Observed
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed
Suspension:	No Damages Observed	Axles:	See Notes		

Engine Details						
Engine Compartment:	No Damages Observed	Oil Dipstick:	Good Level / Dark in Color	Coolant Level:	Good Level	
Engine Serial Plate:	Obstructed					

Observations / Comments

The unit starts and operates.

Disclaimer



Tires Details					
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	Continental	First Left Steer Tire Size:	11R22.5
First Right Steer Steer Tire Condition:	See Notes	First Right Steer Steer Tire Brand:	Continental	First Right Steer Steer Tire Size:	11R22.5
First Left Outer Drive Tire Condition:	No Damages Observed	First Left Outer Drive Tire Brand:	Kumho	First Left Outer Drive Tire Size:	11R22.5
First Left Inner Drive Tire Condition:	No Damages Observed	First Left Inner Drive Tire Brand:	Kumho	First Left Inner Drive Tire Size:	11R22.5
First Right Outer Drive Tire Condition:	No Damages Observed	First Right Outer Drive Tire Brand:	Kumho	First Right Outer Drive Tire Size:	11R22.5
First Right Inner Drive Tire Condition:	No Damages Observed	First Right Inner Drive Tire Brand:	Kumho	First Right Inner Drive Tire Size:	11R22.5































































































































































































































































