



| Inspection Detail              |  |              |                   |
|--------------------------------|--|--------------|-------------------|
| <b>Client:</b>                 | Isuzu Finance                                    |              |                   |
| <b>Inspected by:</b>           | Jesse Herrera                                    |              |                   |
| <b>Location of Inspection:</b> | 8101 Daytona Road NW, Albuquerque, NM 87121, EUA |              |                   |
| <b>Phone No / Email:</b>       | +1 505 839 5900 / esmith@brucknertruck.com       |              |                   |
| <b>Date of Inspection:</b>     | 6/24/2025  | <b>Job#:</b> | 868d9by51         |
| <b>Year:</b>                   | 2022   | <b>Make:</b> | Chevrolet         |
| <b>Model:</b>                  | 17CG33503  | <b>VIN:</b>  | 1GB0GRF71N1271837 |

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Inspection Details**
**Unit Information**

|                            |           |                  |        |                      |     |
|----------------------------|-----------|------------------|--------|----------------------|-----|
| <b>GVWR:</b>               | 9,900 lbs | <b>Odometer:</b> | 24,399 | <b>Engine Hours:</b> | N/A |
| <b>EMS Warning Lights:</b> | No        |                  |        |                      |     |

**Interior Details**

|                           |           |                        |                     |                               |                     |
|---------------------------|-----------|------------------------|---------------------|-------------------------------|---------------------|
| <b>Cab Interior:</b>      | See Notes | <b>Driver's Seat:</b>  | No Damages Observed | <b>Passenger's Seat:</b>      | No Damages Observed |
| <b>Transmission Type:</b> | Automatic | <b>Pedals:</b>         | No Damages Observed | <b>Floorboard:</b>            | No Damages Observed |
| <b>Radio:</b>             | Yes       | <b>A/C:</b>            | Yes                 | <b>Switches and Controls:</b> | No Damages Observed |
| <b>Power Mirrors:</b>     | No        | <b>Heated Mirrors:</b> | No                  | <b>Steering Wheel:</b>        | See Notes           |
| <b>Cab Mirror:</b>        | N/A       | <b>Box Condition:</b>  | See Notes           |                               |                     |

**Exterior Details**

|                        |                     |                      |                     |                     |                     |
|------------------------|---------------------|----------------------|---------------------|---------------------|---------------------|
| <b>Mirrors:</b>        | See Notes           | <b>Steps:</b>        | See Notes           | <b>Handrails:</b>   | No Damages Observed |
| <b>Exhaust System:</b> | No Damages Observed | <b>Front Lights:</b> | No Damages Observed | <b>Rear Lights:</b> | No Damages Observed |
| <b>Suspension:</b>     | No Damages Observed | <b>Axles:</b>        | No Damages Observed |                     |                     |

**Engine Details**

|                             |                     |                      |                            |                       |            |
|-----------------------------|---------------------|----------------------|----------------------------|-----------------------|------------|
| <b>Engine Compartment:</b>  | No Damages Observed | <b>Oil Dipstick:</b> | Good Level / Dark in Color | <b>Coolant Level:</b> | Good Level |
| <b>Engine Serial Plate:</b> | Obstructed          |                      |                            |                       |            |

**Observations / Comments**

The unit starts and operates. The unit was not driven during the time of the inspection, limiting some angles.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

| <b>Tires Details</b>                           |                     |  |             |   |             |
|--|---------------------|--|-------------|---|-------------|
| <b>First Left Steer Tire Condition:</b>        | No Damages Observed | <b>First Left Steer Tire Brand:</b>        | Bridgestone | <b>First Left Steer Tire Size:</b>        | LT245/75R16 |
| <b>First Right Steer Steer Tire Condition:</b> | No Damages Observed | <b>First Right Steer Steer Tire Brand:</b> | Bridgestone | <b>First Right Steer Steer Tire Size:</b> | LT245/75R16 |
| <b>First Left Outer Drive Tire Condition:</b>  | No Damages Observed | <b>First Left Outer Drive Tire Brand:</b>  | Bridgestone | <b>First Left Outer Drive Tire Size:</b>  | LT245/75R16 |
| <b>First Right Outer Drive Tire Condition:</b> | No Damages Observed | <b>First Right Outer Drive Tire Brand:</b> | Bridgestone | <b>First Right Outer Drive Tire Size:</b> | LT245/75R16 |

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Left****Front Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear Left****Rear Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear / Rear Lights****Front / Front Lights****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Left****VIN: 1GB0GRF71N1271837 / GVWR: 9,900 lbs****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**EMS Panel****Odometer: 24,399****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Engine Compartment****Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Coolant / Engine Compartment****Oil Dipstick****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Handrails****Cab Interior****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Driver's Seat****Steering Wheel****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls / Radio / A/C****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Cab Interior****Passenger's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Floorboard****Floorboard****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Pedals / Floorboard****Mirror****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Steps****Handrails****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Handrails****Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Mirror****Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Lights****Front Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear Lights****Rear Lights****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Box Condition****Box Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Steer Tire Condition****First Left Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Steer Tire Size****First Left Steer Tire Condition****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles / Suspension****First Left Outer Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Outer Drive Tire Brand****First Left Outer Drive Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Outer Drive Tire Condition****Axles / Suspension****Disclaimer**



Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Exhaust System****First Right Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Steer Tire Brand****First Right Steer Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles / Suspension****Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Outer Drive Tire Condition****First Right Outer Drive Tire Size****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Outer Drive Tire Brand****First Right Outer Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles / Suspension****Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Axles / Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.