



Inspection Detail			
<b>Client:</b>	Isuzu Finance		
<b>Inspected by:</b>			
<b>Location of Inspection:</b>	6225 State Rd., Philadelphia, PA 19135, USA		
<b>Phone No / Email:</b>	+1 267 255 0956 / jwallick@bentleytruckservices.com		
<b>Date of Inspection:</b>	8/5/2025	<b>Job#:</b>	868f0c0y7
<b>Year:</b>	2020	<b>Make:</b>	Isuzu
<b>Model:</b>	FTR	<b>VIN:</b>	54DK6S161LSG70007

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Inspection Details**
**Unit Information**

<b>GVWR:</b>	25,950	<b>Odometer:</b>	See Notes	<b>Engine Hours:</b>	See Notes
<b>EMS Warning Lights:</b>	NA				

**Interior Details**

<b>Cab Interior:</b>	No Damages Observed	<b>Driver's Seat:</b>	See Notes	<b>Passenger's Seat:</b>	No Damages Observed
<b>Transmission Type:</b>	Automatic	<b>Pedals:</b>	No Damages Observed	<b>Floorboard:</b>	No Damages Observed
<b>Radio:</b>	Yes	<b>A/C:</b>	Yes	<b>Switches and Controls:</b>	No Damages Observed
<b>Power Mirrors:</b>	No	<b>Heated Mirrors:</b>	No	<b>Steering Wheel:</b>	No Damages Observed
<b>Cab Mirror:</b>	N/A	<b>Box Condition:</b>	See Notes		

**Exterior Details**

<b>Mirrors:</b>	No Damages Observed	<b>Steps:</b>	No Damages Observed	<b>Handrails:</b>	No Damages Observed
<b>Exhaust System:</b>	No Damages Observed	<b>Front Lights:</b>	No Damages Observed	<b>Rear Lights:</b>	No Damages Observed
<b>Suspension:</b>	See Notes	<b>Axles:</b>	No Damages Observed		

**Engine Details**

<b>Engine Compartment:</b>	No Damages Observed	<b>Oil Dipstick:</b>	Low Level / Dark in Color	<b>Coolant Level:</b>	Good Level
<b>Engine Serial Plate:</b>	Obstructed				

**Observations / Comments**

The unit does not run or drive due to dead batteries, which prevented us from capturing the EMS panel, odometer, and engine hours. Additionally, limited space prevented capturing the right-side beauty shot, and most beauty shots were affected.

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tires Details					
<b>First Left Steer Tire Condition:</b>	See Notes	<b>First Left Steer Tire Brand:</b>	Ironman	<b>First Left Steer Tire Size:</b>	255/70R22.5
<b>First Right Steer Tire Condition:</b>	No Damages Observed	<b>First Right Steer Tire Brand:</b>	Bridgestone	<b>First Right Steer Tire Size:</b>	255/70R22.5
<b>First Left Outer Drive Tire Condition:</b>	See Notes	<b>First Left Outer Drive Tire Brand:</b>	Yokohama	<b>First Left Outer Drive Tire Size:</b>	255/70R22.5
<b>First Left Inner Drive Tire Condition:</b>	See Notes	<b>First Left Inner Drive Tire Brand:</b>	Yokohama	<b>First Left Inner Drive Tire Size:</b>	255/70R22.5
<b>First Right Outer Drive Tire Condition:</b>	See Notes	<b>First Right Outer Drive Tire Brand:</b>	Yokohama	<b>First Right Outer Drive Tire Size:</b>	255/70R22.5
<b>First Right Inner Drive Tire Condition:</b>	See Notes	<b>First Right Inner Drive Tire Brand:</b>	Yokohama	<b>First Right Inner Drive Tire Size:</b>	255/70R22.5

### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Left****Front Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear Left****Rear Right****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front****Rear****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Rear / Rear Lights****Left****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.




### Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Cab Interior****Unit Information****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Unit Information****Switches and Controls / A/C / Radio****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Passenger's Seat****Cab Interior****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Floorboard****Passenger's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Transmission****Switches and Controls****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Switches and Controls****Switches and Controls****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Steering Wheel****Driver's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Driver's Seat****Driver's Seat****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Driver's Seat****Steering Wheel****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Floorboard****Pedals****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Pedals****Cab Interior****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Cab Interior****Cab Interior****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Cab Interior****Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Mirrors / Handrails****Mirrors****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Front Lights****Front Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Unit Condition****Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Exhaust System****Box Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Box Condition****Box Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension / Axles****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension / Axles****Suspension / Axles****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension / Axles****Suspension / Axles****Disclaimer**



Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension / Axles****Suspension / Axles****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Suspension / Axles****Suspension****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Engine Compartment****Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**Coolant Level**

**Oil Dipstick**

**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Steer Tire Condition****First Left Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Steer Tire Size****First Left Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Steer Tire Condition****First Right Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Steer Tire Size****First Right Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Left Outer Drive Tire Condition / First Left Inner Drive Tire Condition****First Left Outer Drive Tire Condition / First Left Inner Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

## First Left Outer Drive Tire Brand



## First Left Outer Drive Tire Size



## Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Outer Drive Tire Condition****First Right Outer Drive Tire Condition / First Right Inner Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

**First Right Outer Drive Tire Size****First Right Outer Drive Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.