



Aspen Field Services

Job #: 63540 /

VIN: JALC4W160M7006108

DIESEL 2021 ISUZU NPR-HD CAB AND CHASSIS / LA135314

Specifications

Year	2021
Make	Isuzu
Model	NPR-HD
Date of Inspection	11/29/2023
Location of Inspection	3775 Interstate Park Road West, Riviera Beach, FL, 33404
VIN	JALC4W160M7006108
GVWR	14,500 lbs
Odometer	167,402
Engine Hours	3,959
EMS Warning Lights	No Active Warnings
Cab Interior	See Notes
Driver's Seat	No Damages Observed
Passenger's Seat	No Damages Observed
Transmission Type	Automatic
Pedals	No Damages Observed
Floorboard	No Damages Observed
Radio	Yes
A/C	Yes
Switches and Controls	No Damages Observed
Power Mirrors	No
Heated Mirrors	No
Steering Wheel	No Damages Observed
Mirrors	No Damages Observed
Steps	No Damages Observed
Handrails	No Damages Observed
Exhaust Pipe	No Damages Observed
Engine Compartment	See Notes
Oil Dipstick	Good Level / Good Color
Coolant Level	Low Level
Suspension	No Damages Observed
Axles	No Damages Observed
Front Lights	No Damages Observed
Rear Lights	See Notes
Left Steer Tire Condition	No Damages Observed
Left Steer Tire Brand	Firestone
Left Steer Tire Size	LT215/85R16
Left Outer Drive Tire Condition	No Damages Observed
Left Outer Drive Tire Brand	Firestone
Left Outer Drive Tire Size	LT215/85R16
Left Inner Drive Tire Condition	No Damages Observed

Equipment Photo



Video Inspection Link

<https://app.aspenfieldservices.com/jobs/video/44rZE6R6h2FQXDujE>

Notes / Description

Part of the unit's engine information was obtained from a VIN-decoding software.

Aspen Field Services



Front Left / 11-29-2023



Front / Front Lights / 11-29-2023

Aspen Field Services



Front Right / 11-29-2023



Rear Left / 11-29-2023

Aspen Field Services



Rear / Rear Lights / 11-29-2023



Rear Right / 11-29-2023

Aspen Field Services




Left / 11-29-2023



Right / 11-29-2023

Aspen Field Services



VIN: JALC4W160M7006108 / GVWR: 14,500 lbs / Axle Information / 11-29-2023



EMS Warning Lights / 11-29-2023

Aspen Field Services



Odometer: 167,402 / 11-29-2023



Engine Hours: 3,959 / 11-29-2023

Aspen Field Services



Cab Interior / 11-29-2023



Floorboard / 11-29-2023

Steps / 11-29-2023



Handrails / 11-29-2023

Aspen Field Services



Handrails / 11-29-2023



Passenger's Seat / 11-29-2023

Aspen Field Services



Mirrors / 11-29-2023




Handrails / 11-29-2023

Aspen Field Services



Cab Interior / Handrails / 11-29-2023



Floorboard / 11-29-2023

Aspen Field Services



Driver's Seat / 11-29-2023



Steps / 11-29-2023

Aspen Field Services



Pedals / 11-29-2023



Switches and Controls / 11-29-2023

Aspen Field Services



Steering Wheel / 11-29-2023



Switches and Controls / 11-29-2023

Aspen Field Services




Switches and Controls / A/C / Radio / Transmission Type / 11-29-2023




Mirrors / 11-29-2023

Aspen Field Services



Engine Compartment / 11-29-2023



Engine Compartment / 11-29-2023

Aspen Field Services




Oil Dipstick / 11-29-2023



Coolant Level / 11-29-2023

Aspen Field Services



Engine Information / 11-29-2023



Left Steer Tire Condition / 11-29-2023

Aspen Field Services



Left Steer Tire Brand / 11-29-2023



Left Steer Tire Size / 11-29-2023

Aspen Field Services



Left Outer Drive Tire Condition / Left Inner Drive Tire Condition / 11-29-2023



Left Outer Drive Tire Condition / 11-29-2023

Aspen Field Services



Left Outer Drive Tire Brand / 11-29-2023



Left Outer Drive Tire Size / 11-29-2023

Aspen Field Services



Suspension / Axles / 11-29-2023



Right Outer Drive Tire Condition / 11-29-2023

Aspen Field Services



Right Outer Drive Tire Condition / Right Inner Drive Tire Condition / 11-29-2023




Right Outer Drive Tire Brand / 11-29-2023

Aspen Field Services



Right Outer Drive Tire Size / 11-29-2023



Suspension / Axles / 11-29-2023

Aspen Field Services



Exhaust / 11-29-2023



Exhaust / 11-29-2023

Aspen Field Services



Right Steer Tire Condition / 11-29-2023



Right Steer Tire Condition / 11-29-2023

Aspen Field Services



Right Steer Tire Brand / 11-29-2023




Right Steer Tire Size / 11-29-2023

Aspen Field Services



Axles / Suspension / 11-29-2023



Axles / Suspension / 11-29-2023