



[Click to watch the video](#)



Inspection Detail

Client:	Isuzu Finance		
Inspected by:	Andre Knapp		
Location of Inspection:	1015 Timothy Dr, San Jose, CA 95133, USA		
Phone No / Email:	+1 408 674 8157 / dnguyen@monarchtruck.com		
Date of Inspection:	11/14/2025	Job#:	868g8rqck
Year:	2023	Make:	ISUZU
Model:	NRR	VIN:	JALE5W161P7304368

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details									
Unit Information									
GVWR:	19,500 lbs	Odometer:	82,920	Engine Hours:	3,520				
EMS Warning Lights:	Yes								
Interior Details									
Cab Interior:	See Notes	Driver's Seat:	No Damages Observed	Passenger's Seat:	No Damages Observed				
Transmission Type:	Automatic	Pedals:	No Damages Observed	Floorboard:	No Damages Observed				
Radio:	Yes	A/C:	Yes	Switches and Controls:	No Damages Observed				
Power Mirrors:	Yes	Heated Mirrors:	Yes	Steering Wheel:	No Damages Observed				
Cab Mirror:	No Damages Observed	Box Condition:	See Notes						
Exterior Details									
Mirrors:	No Damages Observed	Steps:	No Damages Observed	Handrails:	No Damages Observed				
Exhaust System:	No Damages Observed	Front Lights:	No Damages Observed	Rear Lights:	No Damages Observed				
Suspension:	No Damages Observed	Axles:	No Damages Observed						
Engine Details									
Engine Compartment:	No Damages Observed	Oil Dipstick:	Low Level / Dark in Color	Coolant Level:	Good Level				
Engine Serial Plate:	N/A								
Observations / Comments									
The unit runs and drives.									

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tires Details					
First Left Steer Tire Condition:	No Damages Observed	First Left Steer Tire Brand:	Good Year	First Left Steer Tire Size:	225/70R19.5
First Right Steer Steer Tire Condition:	No Damages Observed	First Right Steer Steer Tire Brand:	Good Year	First Right Steer Steer Tire Size:	225/70R19.5
First Left Outer Drive Tire Condition:	See Notes	First Left Outer Drive Tire Brand:	Hankook	First Left Outer Drive Tire Size:	225/70R19.5
First Left Inner Drive Tire Condition:	No Damages Observed	First Left Inner Drive Tire Brand:	Hankook	First Left Inner Drive Tire Size:	225/70R19.5
First Right Outer Drive Tire Condition:	See Notes	First Right Outer Drive Tire Brand:	Amulet	First Right Outer Drive Tire Size:	225/70R19.5
First Right Inner Drive Tire Condition:	See Notes	First Right Inner Drive Tire Brand:	Amulet	First Right Inner Drive Tire Size:	225/70R19.5

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Wear and Tear Items	
Item Name	Item Comments
First Right Inner Drive Tire Condition	The tire appears to have low tread, and the tire can be replaced.
First Right Outer Drive Tire Condition	The tire appears to have low tread.
First Left Outer Drive Tire Condition	The tire appears to have low tread.
ABS Light	The unit has an active ABS light and a traction control light, and it will need diagnostics and repairs.
Windshield	The windshield is cracked and will need to be replaced.
Engine Oil	The engine oil is dark and low, and the unit will need a full service.
Right Box top trim	The very top of the box where the top marker lights are mounted on the edge has multiple small bends, and it will need repairs or replacement.
Right Side Panels	The right box side panels are scratched.
Left Side Panels	The left side panels for the box are damaged and will need repairs or replacement.
Paint	The unit has minor paint damage.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front Left**Front Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Rear Left**Rear Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front**Rear****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left**Right****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

VIN: JALE5W161P7304368**GVWR: 19,500 lbs****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Odometer: 82,920**EMS Panel****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

EMS Panel



Engine Hours: 3,520



Disclaimer


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Cab Interior**Steering Wheel****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Transmission Shifter**Switches and Controls****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls**A/C / Radio****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Switches and Controls**Driver's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Floorboard**Pedals****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Passenger's Seat**Passenger's Seat****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Handrails**Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Mirrors**Handrails****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Mirrors**Steps****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Front Lights**Front Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Rear Lights**Rear Lights****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Undercarriage**Undercarriage****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Exhaust System**Exhaust System****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Box Interior**Box Interior****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Axles / Suspensions**Axles / Suspensions****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Axles / Suspensions**Axles / Suspensions****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Engine Compartment**Engine Compartment****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Coolant**Oil Dipstick****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Steer Tire Condition**Left Steer Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Left Steer Tire Size**Left Steer Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Outer Drive Tire Condition**First Left Outer Drive Tire Brand****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Left Outer Drive Tire Size**First Left Outer Drive Tire Condition / First Left Inner Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Suspensions**Right Steer Tire Condition****Disclaimer**


Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Steer Tire Brand**Right Steer Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Right Steer Tire Condition**First Right Outer Drive Tire Condition****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Outer Drive Tire Brand**First Right Outer Drive Tire Size****Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

First Right Outer Drive Tire Condition / First Right Inner Drive Tire Condition**Disclaimer**

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.