



BLACK ROCK TRUCK GROUP, INC
YONKERS ID#7118860
257 LAKE AVE
YONKERS, NY 10701
P: (914) 979-2853
Dealer Code: DEXD

Connecticut: Branford
New York: Yonkers

Visit our web site at www.blackrocktruck.com

SERVICE ORDER



R200025233

Bill-To Customer

29441

Owner

29441

ISUZU FINANCE OF AMERICA, INC.
2500 WESTCHESTER AVE STE 312
PURCHASE NY 10577

ISUZU FINANCE OF AMERICA, INC.
2500 WESTCHESTER AVE STE 312
PURCHASE NY 10577

Customer Phone: (866) 914-9557

DATE ARRIVED	SALES TYPE	TERMS	ID	ADVISOR	CUSTOMER PO	DATE INVOICE	
8/10/2026 1:34PM	SCH	NET30	M7005608	MICHAEL			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	IN SERVICE	ODOM IN	ODOM OUT
2021	ISUZU	NPR-HD	JALC4W164M7005608	RENTAL 2	02/14/2020	63,029	0

Sold Operations

JOB #1 VHR PULL VEHICLE HEALTH REPORT

COMPLAINT PULL VEHICLE HEALTH REPORT

PULL VEHICLE HEALTH REPORT. \$300 PLUS TAXES, ETC. NEEDS TIRE AND BRAKE PERCENTAGES RECORDED PER CHECK LIST

7/24-d.Kurosaki@isuzufin.com AUTHORIZED ADDITIONAL LETTERING REMOVAL FOR COST OF \$50. PLUS TAX

CAUSE SEND REPORTS TO mbeauton@blackrocktruck.com
PER REQUEST

CORRECTION PLUG INTO TRUCK AND RUN THROUGH HEALTH REPORT. CEL LIGHT ON, NEED TO DIAGNOSE
PULLED AND SENT HEALTH REPORT. RECORDED TIRE AND BRAKE MEASUREMENTS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR			260.00

Parts: \$0.00 Labor: \$260.00 Misc: \$0.00 Sublet: \$0.00 \$260.00

JOB #2 CEL CHECK AND ADVISE FOR CHECK ENGINE LIGHT

COMPLAINT CHECK AND ADVISE FOR CHECK ENGINE LIGHT

NEED TO QUOTE CUTOMER!!!

CAUSE BAD GROUNDS

CORRECTION CHECKED ENGINE FAULTS USING THE COMPUTER VIA IDSS, FOUND INACTIVE FAULT CODES P0045, P2563, P156A, P2049, AND P1464. FAULTS P0045 "TURBOCHARGER BOOST CONTROL SOLENOID CIRCUIT, AND P2563 "TURBOCHARGER VANE POSITION SENSOR PERFORMANCE .DISCONNECTED BATTERIES, REMOVED AND CLEANED CHASSIS GROUNDS, TIGHTEN ALL GROUNDS. RECONNECTED BATTERIES AND TIGHTENED THEM. PUT TRUCK OUTSIDE TO PERFORM REGEN, AFTER NO ACTIVE FAULTS CAME UP.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR			262.80

Parts: \$0.00 Labor: \$262.80 Misc: \$0.00 Sublet: \$0.00 \$262.80



BLACK ROCK TRUCK GROUP, INC
YONKERS ID#7118860
257 LAKE AVE

SERVICE ORDER: R200025233

REFERENCE: E200018150:01

Sold Operations (Cont.)

JOB #3 DE-IDEN' REMOVE LETTERING OFF TRUCK

COMPLAINT REMOVE LETTERING OFF TRUCK
CAUSE REMOVE LETTERING AND EMAIL PICTURES OF TRUCK AS INSTRUCTED
CORRECTION 2-REMOVED LETTERING. SENT ALL PICTURES REQUESTED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	REPAIR	REMOVE LETTERING	90.00	90.00
Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$90.00				\$90.00

JOB #4 RT ROAD TEST AND CHECK WORK PERFORMED ON VEHICLE.

COMPLAINT ROAD TEST AND CHECK WORK PERFORMED ON VEHICLE.
CAUSE
CORRECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR			0.00
Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00				\$0.00

Sold Operations Totals **Parts: \$0.00 Labor: \$522.80 Misc: \$0.00 Sublet: \$90.00 \$612.80**

PARTS AND SERVICE HOURS
Weekdays 7AM - 5PM, Sat & Sun Closed

	ESTIMATED	BILLED
LABOR		\$522.80
PARTS		\$0.00
MISC		\$0.00
SUBLET		\$90.00
SUBTOTAL		\$612.80

SHOP SUPPLIES \$78.42
MISC SUPPLIES \$0.00
TAX \$61.35
TOTAL \$752.57

AUTHORIZED BY: _____ DATE: _____

PRINT: _____ EMAIL: d.Kurosaki@isuzufin.com

JE: 2323995

Please Remit to:
Black Rock Truck Group
15 E. Industrial Rd
Branford, CT 06405